



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Ref: CS/ASM21009089/Ktc	
			Date: 30/08/2021	
			Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	YP 5661D	Veh. Inspected	SKW 5182Z
	Policy No.		Coverage (\$)	0.00
	Claim No.	S1M03GKK	Excess (\$)	0.00
	Assign From	KHONG LYNN	Assign Date	30/08/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
	Accident Date	26/08/2021	Inspection Date	30/08/2021
	Survey held at	160 Sin Ming Drive #08-03 Sin Ming AutoCity		
	Repairer	T & B MOTOR REPAIRS SERVICES PTE LTD		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			