

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2108-180 TG

DATE : 30-Aug-2021

POLICY NO. : P10555823R00

VEHICLE REG. NO. : SJU2418L

VEHICLE MAKE : HYUNDAI AVANTE 1.6 AT ABS D/AB 2WC

TO Motor Claim Department

India International Insurance Pte Ltd

64 Cecil Street, #04-#05 IOB Building

Singapore 049711

Tel: 6347 6100 Fax: 6224 4174 / 6225 7743

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	SPARE PARTS			
1	Front Bumper <i>de</i>	1	\$ 650.00	\$ 650.00
2	Front Bumper Clips <i>na</i>	10	\$ 3.00	\$ 30.00
3	Front Bumper Retainer RH <i>2x</i>	1	\$ 50.00	\$ 50.00
4	Front Bumper Retainer LH <i>x</i>	1	\$ 50.00	\$ 50.00
5	Front Reinforcement <i>!</i>	1	\$ 350.00	\$ 350.00
6	Front Sponge <i>?</i>	1	\$ 120.00	\$ 120.00
7	Front Grille Assy <i>2?</i>	1	\$ 380.00	\$ 380.00
8	Front Lower Grille (Center) <i>2?</i>	1	\$ 200.00	\$ 200.00
9	Front Support Panel <i>x</i>	1	\$ 620.00	\$ 620.00
10	Foglamp Garnish RH <i>x</i>	1	\$ 40.00	\$ 40.00
11	Foglamp Garnish LH <i>x</i>	1	\$ 40.00	\$ 40.00
12	Headlamp RH <i>x</i>	1	\$ 350.00	\$ 350.00
13	Headlamp LH <i>x</i>	1	\$ 350.00	\$ 350.00
14	Rear Bumper <i>de</i>	1	\$ 680.00	\$ 680.00
15	Rear Bumper Clips <i>na</i>	10	\$ 3.00	\$ 30.00
16	Rear Bumper Retainer RH <i>cm</i>	1	\$ 50.00	\$ 50.00
17	Rear Bumper Retainer LH <i>x</i>	1	\$ 50.00	\$ 50.00
18	Rear Reinforcement <i>!</i>	1	\$ 380.00	\$ 380.00
19	Rear Sponge <i>?</i>	1	\$ 130.00	\$ 130.00
20	Rear Tail lamp RH <i>?</i>	1	\$ 280.00	\$ 280.00
21	Rear Bootlip lamp RH <i>x</i>	1	\$ 230.00	\$ 230.00
22	Rear Bootlid <i>repair</i>	1	\$ 1,150.00	\$ 1,150.00
23	Rear Bootlid Lock <i>x</i>	1	\$ 120.00	\$ 120.00
24	Rear Bootlid Rubber Seal <i>x</i>	1	\$ 80.00	\$ 80.00
25	Rear Bootlid Outer Chrome Garnish <i>x</i>	1	\$ 80.00	\$ 80.00
26	Rear Hyundai Emblem <i>na</i>	1	\$ 50.00	\$ 50.00
27	Rear Avante Emblem <i>na</i>	1	\$ 50.00	\$ 50.00
28	End Panel <i>repair</i>	1	\$ 550.00	\$ 550.00
29	End Panel Garnish <i>x</i>	1	\$ 60.00	\$ 60.00
30	Engine Mount RH <i>x</i>	1	\$ 250.00	\$ 250.00
Total Spare Parts				\$ 7,450.00

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2108-180 TG

DATE : 30-Aug-2021

POLICY NO. : P10555823R00

VEHICLE REG. NO. : SJU2418L

VEHICLE MAKE : HYUNDAI AVANTE 1.6 AT ABS D/AB ZWE

TO Motor Claim Department

India International Insurance Pte Ltd

64 Cecil Street, #04-#05 IOB Building

Singapore 049711

Tel: 6347 6100 Fax: 6224 4174 / 6225 7743

FOR SURVEYOR

RASU - Hp 90010068
7 days - L/S - 30/08/21 @ 1730
Reg after repair

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPECIAL NETT				
31	Front License Plate With Casing <i>64</i>	1	\$ 40.00	\$ 40.00 <i>35</i>
32	Rear License Plate With Casing <i>X</i>	1	\$ 40.00	\$ 40.00
33	Reverse Sensor <i>?</i>	2	\$ 200.00	\$ 400.00 <i>200?</i>
Total Special Nett				\$ 480.00
LABOUR				
34	Spray Paint (Front Bumper, Bonnet, Rear Bumper & Bootlid)	1	\$ 1,000.00	\$ 1,000.00 <i>800</i>
35	Remove and Refit Affected Accident Area	1	\$ 1,000.00	\$ 1,000.00 <i>600-700</i>
36	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 80.00	\$ 80.00 <i>60</i>
37	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00 <i>X</i>
38	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00 <i>✓</i>
Total Labour				\$ 2,210.00
Amount Before Excess				\$ 10,140.00
Add GST @ 7%				709.80
Total Amount Payable				\$ 10,849.80

Estimate prepared by: Ken Ho

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: