



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
NTUC INCOME INSURANCE CO-OPERATIVE LTD C/O : LOW YEAP TOH & GOON LLP 20 MAXWELL ROAD, 12-01 MAXWELL HOUSE, SINGAPORE 069113SINGAPORE 189556			Ref: CS/INC21009094/Gqf3e2 Date: 22/10/2021 Code: INC	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	SBV 101C	Veh. Inspected	SLF 2167R	
Policy No.		Coverage (\$)	0.00	
Claim No.	MT/0993921-005/TTK	Excess (\$)	0.00	
Assign From	SITI MARINA	Assign Date	30/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA SIENTA 1.5G	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	NSP1707016602	Colour	BROWN	
Odometer	52018 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	FALKEN	6 mm	
L/H Front Tyre	185/60 R15	FALKEN	6 mm	
R/H Rear Tyre	185/60 R15	FALKEN	6 mm	
L/H Rear Tyre	185/60 R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	10/05/2018	Inspection Date	10/09/2021	
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			13 Working Days	