

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21009095/KPS3Q2
Date: 15/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800153482
Claimant Vehicle No :	SMR3276C	Insured Vehicle No :	SJL7866R
Date of Loss:	27/08/2021	Nature of Claim:	TP
		Claim No:	0863028305SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR3276C		
Make & Model:	NISSAN SERENA, 2.0 (A)	Engine No:	HR12128301K
Reg. Date:	30/12/2019 (Man. Year: 2019)	Chassis No:	JN1EBAC27Z0000365
Colour:	Metallic Grey	Odometer:	42775 km
Engine Capacity:	1198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,136.20	4,565.07	1,571.13	25.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,220.00	1,210.00	1,010.00	45.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,356.20	5,775.07	2,581.13	30.89
+ GST 7.00/7.00% (S\$)	584.93	404.25	180.68	30.89

Nett Amount (S\$)	8,941.13	6,179.32	2,761.81	30.89
+ Car Rental (4.0 x S\$60.00/day + 7.00% GST) (S\$)		256.80		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,443.57		
Global Sum Settlement (S\$)		6,440.00		

INSPECTION

Date of Assignment: 30/08/2021

Date Inspected: 31/08/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Hui Yang Motor Pte Ltd (HQ)
 176 Sin Ming Drive #04-02, Sin Ming AutoCare
 Singapore 575721

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT CENTRE GRILLE	Mtg Cracked	727.90 FN	*721.60 FN
2	1		*FRONT BUMPER	Buckled / Cracked	765.60 FN	*565.50 FN
3	1		*FRONT BUMPER NUMBER GARNISH	No such part	186.90 FN	*- FN
4	1		*FRONT BUMPER SPONGE	Cracked	168.50 FN	*168.50 FN
5	1		*FRONT BUMPER REINFORCEMENT	Bent	548.50 FN	*410.90 FN
6	1		*FRONT BUMPER LH SIDE RETAINER	Distorted	38.70 FN	*38.70 FN
7	1		*FRONT BUMPER LH FOG LAMP	Mtg Cracked	385.40 FN	*385.40 FN
8	1		*FRONT BUMPER LH FOG LAMP GARNISH	Dented / Cut	129.70 FN	*129.70 FN
9	1		*FRONT BUMPER LH PARKING SENSOR	Shorted	232.00 FN	*232.00 FN
10	1		*FRONT LH HEADLAMP	Mtg Cracked	1,839.60 FN	*1,739.90 FN
11	1		*FRONT LH HEADLAMP CHROME	Serviceable	150.20 FN	*- FN
12	1		*FRONT LH SIGN LAMP	Serviceable	785.20 FN	*- FN
13	1		*FRONT LH FENDER	Buckled	680.10 FN	*680.10 FN
14	1		*FRONT LH FENDER INNER SHIELD	Serviceable	129.70 FN	*- FN
15	10		*FRONT LH FENDER INNER SHIELD CLIP	Not Necessary	50.00 FN	*- FN
F=Franchise part. N=NettItemDisc.						
Sub Total (\$\$)					6,818.00	5,072.30
- Nett Item Discount on N Items 10.00/10.00% (\$\$)					681.80	507.23
Total Parts (\$\$)					6,136.20	4,565.07

F=Franchise part. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	ALIGNMENT	New	60.00	0.00
2	WIRING	New	80.00	20.00
3	TUFFKOTE	New	80.00	30.00
4	SPRAY PAINTING	New	1,000.00	660.00
5	LABOUR CHARGES	New	1,000.00	500.00
Gross Labour Cost (S\$)			2,220.00	1,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >