

A19

# 輝陽汽車有限公司

## HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

27/08/2021

Owner: NEO LAY HOON

### ESTIMATE TO REPAIR NISSAN SERENA - SMR3276C

|       |                                           |      |    |          |
|-------|-------------------------------------------|------|----|----------|
| 1pc   | front centre grille                       | nett | \$ | 727.90   |
| 1pc   | front bumper                              | nett | \$ | 765.60   |
| 1pc   | front bumper number garnish               | nett | \$ | 186.90   |
| 1pc   | front bumper sponge                       | nett | \$ | 168.50   |
| 1pc   | front bumper reinforcement                | nett | \$ | 548.50   |
| 1pc   | front bumper LH side retainer             | nett | \$ | 38.70    |
| 1pc   | front bumper LH fog lamp                  | nett | \$ | 385.40   |
| 1pc   | front bumper LH fog lamp garnish          | nett | \$ | 129.70   |
| 1pc   | front bumper LH parking sensor            | nett | \$ | 232.00   |
| 1pc   | front LH headlamp                         | nett | \$ | 1,839.60 |
| 1pc   | front LH headlamp chrome                  | nett | \$ | 150.20   |
| 1pc   | front LH sign lamp                        | nett | \$ | 785.20   |
| 1pc   | front LH fender                           | nett | \$ | 680.10   |
| 1pc   | front LH fender inner shield              | nett | \$ | 129.70   |
| 10pcs | front LH fender inner shield clip @\$5.00 | nett | \$ | 50.00    |

|          |    |          |
|----------|----|----------|
|          | \$ | 6,818.00 |
| less 10% | \$ | 681.80   |
|          | \$ | 6,136.20 |

|                |    |          |
|----------------|----|----------|
| alignment      | \$ | 60.00    |
| wiring         | \$ | 80.00    |
| tuffkote       | \$ | 80.00    |
| spray painting | \$ | 1,000.00 |
| labour charges | \$ | 1,000.00 |
| Total          | \$ | 8,356.20 |

