



REF: 677/21-02

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Bldg 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) Fax: 64514658

GST & Reg No. 201629438M

27/08/2021

85775-07

Not Authorised

Resurvey, B4 paint

JN1EBAC2720000365

4 days

Owner: NEO LAY HOON

ESTIMATE TO REPAIR NISSAN SERENA - SMR3276C

1pc	front centre grille → 721-60	mycom	nett	\$	727.90	✓
1pc	front bumper → 565.90	Bulcom	nett	\$	765.60	✓
1pc	front bumper number garnish	NIP	nett	\$	186.90	X
1pc	front bumper sponge	CM	nett	\$	168.50	✓
1pc	front bumper reinforcement 400.00 410.90	A1	nett	\$	548.50	✓
1pc	front bumper LH side retainer	D17	nett	\$	38.70	✓
1pc	front bumper LH fog lamp	mycom	nett	\$	385.40	X ✓
1pc	front bumper LH fog lamp garnish	Autlw	nett	\$	129.70	✓
1pc	front bumper LH parking sensor	Shan	nett	\$	232.00	✓
1pc	front LH headlamp → 1739.90	mycom	nett	\$	1,839.60	✓
1pc	front LH headlamp chrome	in	nett	\$	150.20	X
1pc	front LH sign lamp	in	nett	\$	785.20	X
1pc	front LH fender	Bu	nett	\$	680.10	✓
1pc	front LH fender inner shield	in	nett	\$	129.70	X
10pcs	front LH fender inner shield clip @\$5.00	nn	nett	\$	50.00	X

less 10%

\$ 6,818.00

\$ 681.80

\$ 6,136.20

alignment
wiring
tuffkote
spray painting
labour charges
Total

nn \$ 60.00 X
\$ 80.00 201
\$ 80.00 301
\$ 1,000.00 6601
\$ 1,000.00 5001
\$ 8,356.20



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: