

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/III21009104/KRA3Q2

Date:

08/12/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D19MCV0004060_01

Claimant Vehicle No : SKC81U**Insured Vehicle No :**

GBH7196G

Date of Loss: 27/08/2021

Nature of Claim:

TP

Claim No:

MCV2021D0003721

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKC81U**

Make & Model: BMW 216D, 1.5 D GRAN TOURER LED NAV 7 SEATER (A)

Engine No: 30669518B37C15A

Reg. Date: 01/06/2016 (Man. Year: 2016)

Chassis No: WBA2E320205B44838

Colour: White

Odometer: 190324 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size:

215/55 R17

Front Left Side: Pirelli 3 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side: Pirelli 3 mm

Rear Right Side:

Pirelli 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,083.86	6,717.03	1,366.83	16.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,610.00	1,130.00	480.00	29.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,693.86	7,847.03	1,846.83	19.05
Approved Total (Overridden) (S\$)		6,250.00		

(S\$)	9,693.86	6,250.00	3,443.86	35.53
+ GST 7.00/7.00% (S\$)	678.57	437.50	241.07	35.53
Nett Amount (S\$)	10,372.43	6,687.50	3,684.93	35.53
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,394.95		

INSPECTION

Date of Assignment: 30/08/2021

Date Inspected: 01/09/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Bifrost Auto Pte Ltd (HQ)
176 Sin Ming Drive, #03-09
Singapore 575721

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Nov 2021)
Parts:	M1-MPV	BMW 216D 1.5 D GRAN TOURER LED NAV 7 SEATER (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKC81U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	901.75 F	*901.75 FL
2	1		*FRONT BUMPER BRACKET	Distorted	40.00 F	*40.00 FL
3	2		*FRONT BUMPER SENSOR	Shorted	502.60 F	*502.60 FL
4	1		*FRONT BUMPER FOG LAMP	Serviceable	301.80 F	*- FL
5	1		*FRONT BUMPER FOG LAMP COVER	Dented	95.66 F	*95.66 FL
6	1		*O/S HEAD LAMP	Cut	2,363.65 F	*2,359.75 FL
7	1		*O/S FRONT FENDER	Bent	630.25 F	*630.25 FL
8	1		*O/S FRONT FENDER EMBLEM	Necessary	71.30 F	*71.30 FL
9	1		*O/S FRONT FENDER UNDER SHIELD	Serviceable	135.60 F	*- FL
10	1		*O/S FROMT RIM	Dented	805.90 F	*805.90 FL
11	1		*O/S FROMT SHOCK ABSORBER	Bent	308.45 F	*308.45 FL
12	1		*O/S FRONT KNUCKLE BEARING (WITH/HUB)	Necessary	511.30 F	*511.30 FL
13	1		*O/S FRONT KNUCKLE ARM	Bent	557.45 F	*557.45 FL
14	1		*O/S FRONT LOWER ARM	Distorted	286.15 F	*286.15 FL
15	1		*O/S FRONT LOWER ARM BUSH	Not Necessary	192.00 F	*- FL
16	1		*O/S FRONT TYRE	Serviceable	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,083.86	7,070.56
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	353.53
Total Parts (\$\$)	8,083.86	6,717.03

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PUTTY & SPRAY PAINTING	New	600.00	450.00
2	TO CHECK FRONT WIRING & FOCUS HEADLIGHT	New	30.00	20.00
3	TO CHECK WHEEL ALIGNMENT	New	80.00	60.00
4	TO REPLACE FRONT UNDER CARRIAGE	New	400.00	200.00
5	LABOUR	New	500.00	400.00
Gross Labour Cost (S\$)			1,610.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >