

CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883

Email: admin@cnmotorspl.com

Tel: 6509 5545 Fax: 6509 5567

UEN: 202026492W GST Reg No: 202026492W

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 28/08/2021

30/08/2021

TP LonPac

Jeslin

Estimated repair cost for vehicle no : SGR1919R MAZDA CX-3 SKYACTIV-G 2.0 6 AT 2WD SR

CHASSIS: JM6DK2W7AH0127524 (2016)

S/N	Qty	Items	U/price	Amount
1	1	REAR TAILGATE <i>Dented</i>	\$1,090.00	\$1,090.00 ✓
2	1	REAR TAILGATE LOCK <i>Dented</i>	\$213.00	\$213.00 ✓
3	1	REAR TAILGATE INNER TRIM BOARD <i>cracked</i>	\$217.00	\$217.00 ✓
4	2	REAR TAILGATE NUMBER PLATE LAMP <i>cracked</i>	\$75.00	\$150.00 ✓
5	1	REAR TAILGATE LOCK SENSOR <i>Dented</i>	\$110.00	\$110.00 ✓
6	2	REAR TAILGATE LOCK OPEN SWITCH <i>Dented</i>	\$178.00	\$178.00 ✓
7	2	REAR TAILGATE LAMP broken CUT	\$676.00	\$1,352.00 ✓
8	1	REAR TAILGATE EMBLEM LOGO <i>Free</i>	\$55.00	\$55.00 ✓
9	1	REAR TAILGATE EMBLEM CX 3	\$56.00	\$56.00 ✓
10	1	REAR BUMPER <i>Distorted</i>	\$1,089.00	\$1,089.00 ✓
11	1	REAR BUMPER REINFORCEMENT <i>Best.</i>	\$363.00	\$363.00 ✓
12	2	REAR BUMPER SIDE RETAINER <i>new</i>	\$25.00	\$50.00 ✓
13	2	REAR BUMPER REFLECTOR <i>cracked</i>	\$145.00	\$290.00 ✓
14	2	REAR BUMPER REFLECTOR BRACKET <i>Dented</i>	\$81.00	\$162.00 ✓
15	1	REAR BUMPER LOWER CENTER BRACKET <i>Dented</i>	\$43.00	\$43.00 ✓
16	4	REAR BUMPER REVERSE SENSOR <i>Dented. 2 pieces</i>	\$136.00	\$544.00 272
17	1	REAR BUMPER REVERSE SENSOR WIRE HARNESS <i>new</i>	\$120.00	\$120.00 +
18	1	REAR END PANEL <i>Dented</i>	\$486.00	\$486.00 ✓
19	1	REAR END PANEL TOP GARNISH <i>Delint</i>	\$87.00	\$87.00 ✓
20	2	REAR TAILLAMP <i>Ripped</i>	\$1,505.00	\$3,010.00 1505
21	2	REAR TAILLAMP LOWER BRACKET <i>new</i>	\$38.00	\$38.00 +
22	1	REAR EXHUAUST MUFFLER <i>Best</i>	\$1,350.00	\$1,350.00 1185
23	2	REAR EXHUAUST MUFFLER RUBBER MOUNTING <i>new</i>	\$35.00	\$70.00 +
24	1	REAR EXHUAUST MUFFLER SHIELD <i>cracked</i>	\$63.00	\$63.00 ✓
25	1	REAR REVERSE CAMERA <i>Dented</i>	\$756.00	\$756.00 400 (SN)
26	1	RH REAR WHEEL ARCH GARNISH <i>new</i>	\$71.00	\$71.00 +

9066

S.N. 1400

721280

LESS 20 % \$2,402.60
SUB-TOTAL : \$9,610.40

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	REAR BUMPER CLIPS <i>Nkr</i>	\$60.00	\$60.00 <i>30</i>
2	1	REAR END PANEL SEALANT <i>Nkr</i>	\$80.00	\$80.00 <i>60</i>
3	1	REAR TAILGATE WINDSCREEN GLASS SEALANT <i>Nkr</i>	\$100.00	\$100.00 <i>60</i>
4	2	REAR TAILLAMP CLIPS <i>Nkr</i>	\$40.00	\$80.00 <i>20</i>
5	1	REAR NUMBER PLATE WITH CASING <i>included</i>	\$60.00	\$60.00 <i>✓</i>
6	1	<i>Spere Tyre Compartment Panel Insulation Pad</i>	<i>300</i>	<i>20</i> TOTAL: <u>\$380.00</u>
		<i>Nkr</i>		TOTAL PARTS : <u>\$9,990.40</u>

Labour charges

1	LABOUR FOR PANEL BEATING	<i>430</i>	\$1,800.00 <i>1300</i>
2	LABOUR FOR SPRAYPAINTING		\$1,200.00 <i>1000</i>
3	LABOUR FOR REMOVE & REFIX REAR WINDSCREEN GLASS		\$120.00 <i>✓</i>
4	LABOUR FOR REMOVE & TRANSFER ALL REAR TAILGATE FITTING	<i>2810</i>	\$250.00 <i>20</i>
5	WIRING CHECK		\$80.00 <i>30</i>
7	LABOUR FOR REMOVE & RENEW REAR EXHUAUST MUFFLER / TO REPAIR & STRAIGHTEN REAR EXHUAUST PIPE		\$300.00 <i>80</i>
8	TO APPLY RUST PROOF / TUFF COAT ON ACCIDENT AREAS		\$300.00 <i>100</i>
			Subtotal :- <u>\$4,050.00</u>

Total:- \$14,040.40

Adrian C
F/S 31/08/21.

09 Days.

Supplementary
: 1459.20

total: 123120

l/s 9.8k

9.8k

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883

Email: admin@cnmotorspl.com

Tel: 6509 5545 Fax: 6509 5567

UEN: 202026492W GST Reg No: 202026492W

Blk 1 Kaki Bukit Ave 6

30/08/2021

01-43

Singapore 417883

Accident date : 28/08/2021

Estimated repair cost for vehicle no : SGR1919R MAZDA CX-3 SKYACTIV-G 2.0 6 AT 2WD SR

CHASSIS: JM6DK2W7AH0127524 (2016)

SUPPLEMENTARY ITEMS

S/N	Qty	Items	U/price	Amount
1	1	REAR BUMPER LOWER CENTER BRACKET (EXTENSION) <i>Rep</i>	\$48.00	\$96.00 ✓
2	2	SENSOR MODULE BRACKET <i>cracked</i>	\$87.00	\$174.00 ✓
3	1	REAR SPARE TYRE COMPARTMENT PANEL <i>Buckled</i>	\$897	\$897 ✓
4	2	RH REAR FENDER AIR VENT <i>cracked</i>	\$75.00	\$150.00 ✓
5	1	REAR KEYLESS SENSOR <i>Damaged</i>	\$112.00	\$112.00 ✓
6	2	Rear Fender Inner Trim Board <i>RH cracked</i>	395	790 ✓ <i>395</i>
			TOTAL :	\$1,255.00
			LESS 20 %	\$251.00
			SUB-TOTAL :	\$1,004.00

1824

Supplementary : 1855.20