



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2203671

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 14/06/2022
Reference CC4/LPC21009109/Rea3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SLM 8471K
Insured Veh. SMM 4818J
Claim No. 20/21/21/VP05/024903
Policy No. Z20VP05027817
Accident Date 28/08/2021
Inspection Date 30/08/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21009109/Rea3q2 Date: 14/06/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMM 4818J	Veh. Inspected	SLM 8471K	
Policy No.	Z20VP05027817	Coverage (\$)	0.00	
Claim No.	20/21/21/VP05/024903	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	30/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA RIUS HYBRID 1.8 CVT	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU803554660	Colour	WHITE	
Odometer	261604 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	DUNLOP	6 mm	
L/H Front Tyre	195/65 R15	DUNLOP	6 mm	
R/H Rear Tyre	195/65 R15	DUNLOP	6 mm	
L/H Rear Tyre	195/65 R15	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/08/2021	Inspection Date	30/08/2021	
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 8471K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
1	REINFORCEMENT (SN)	SERVICEABLE	336.30	-
1	RETAINER ,RR BUMPER (SN)	NECESSARY	118.90	118.90
1	COVER,RR BUMPER (SN)	DEFORMED	447.20	447.20
1	COVER,RR BUMPER (SN)	DEFORMED	15.50	15.50
1	GUARD ,RR BUMPER (SN)	DEFORMED	582.20	582.20
13	PIECE ,RR BUMPER (SN)	NECESSARY	53.30	53.30
1	FILLER ,RR BUMPER (SN)	CRACKED	124.90	124.90
1	LENS & BODY,RR (SN)	SCRATCHED	506.70	506.70
1	GARNISH SUB-ASSY (SN)	TO REPAIR SEE LABOUR	937.60	-
1	PLATE ,LUGGAGE (SN)	NECESSARY	48.40	48.40
1	PLATE ,LUGGAGE COMPT (SN)	NECESSARY	55.20	55.20
			3,326.20	2,002.30
	<u>LABOUR</u>			
	CHECK WIRING AND CONDUCT LEAK TEST.		180.00	180.00
	DRILL HOLE AND INSTALL REVERSE SENSOR .		180.00	180.00
	RESET ECU.		180.00	180.00
	REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA.INCLUSIVE OF THE REPAIR OF GARNISH SUB-ASSY.		2,160.00	1,440.00
	RESPRAY ACC AFF AREA.		1,770.00	1,180.00
			4,470.00	3,160.00
	GRAND TOTAL		7,796.20	5,162.30
	RECOMMENDED COST OF REPAIRS			5,162.30

Report Ref No. CC4/LPC21009109/Rea3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLM 8471K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLM 8471K

RE-INSPECTION

