

(08/11/13) wef

ASS. REC. BY: Rue

REF:

CC4/LPC2100 9109/R16a3

C  
2006**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLM 8471Kat Workshop m/s BORNEO MOTORof 2 PANDAN CRESCENTInsured: LPC

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 68K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLM 8471K Yr Regn: 2011 / APRType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA PRIUS HYBRID 1.8 CVT C.C 1798Colour: WHITE A/C: Insured / Std / NI / NASp. Reading: 261604 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTOKB3FU803554660Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: a ~BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 28/08/21 D.O.I. 30/08/21Survey held at BORNEO MOTOR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time \_\_\_\_\_ Action / Instruction \_\_\_\_\_

Repair limit - 34K

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report☐ : Final Report

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

\_\_\_\_\_ S + RS \_\_\_\_\_ SI

Photos

Others

TOTAL

Report Format : \_\_\_\_\_

Lump Sum / I.B.I. (\$) \_\_\_\_\_ )

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_ )☐ : Interview (\$ \_\_\_\_\_ )☐ : Tech. Invs (\$ \_\_\_\_\_ )☐ : Weekend (\$ \_\_\_\_\_ )



# Borneo Motors

Inchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
No. 2 PANDAN CRESCENT  
SINGAPORE 128462, Tel no.: 6631 1188



# TOYOTA

## ESTIMATE

| Account Details   | Account No.                 | Customer Details                                                                               |
|-------------------|-----------------------------|------------------------------------------------------------------------------------------------|
| THIRD PARTY CLAIM | S1000020 / TPCLAIM          | M/S Grab Rentals Pte Ltd<br>6 Battery Road<br>#38-04<br>Singapore 049909<br><br>Work: 65703925 |
|                   | Document No.<br>0           |                                                                                                |
|                   | Document Date<br>28/08/2021 |                                                                                                |

| Year | Model  | Variant   | Reg. Date  | Reg. No. | Kilometers | Wip No. | Order No. / Remarks  |
|------|--------|-----------|------------|----------|------------|---------|----------------------|
| 2017 | ZVW50R | AHXEBW Q3 | 13/04/2017 | SLM8471K | 0          | 64351   | 66TP/SLM8471K/280821 |

| Chassis No.       | Engine No. | Terms | SA / Counter | Vehicle In | Collected On         |
|-------------------|------------|-------|--------------|------------|----------------------|
| JTDKB3FU803554660 | 2ZRS031607 | 60    | Shashitharan | --/--/---- | 0.00 --/--/---- 0.00 |

| L  | Cd | Job/Parts Description                                                                                                                                                                          | Qty  | Unit Price | Disc % | Amount       |
|----|----|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|------------|--------|--------------|
| 1  | Z  | BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR<br>TP VEH NO.:SMM4818J ACC DATE:28/08/21<br>DRIVE IN:28/08/21 EXCESS:<br>DATE-IN: DATE SURVEY:<br>NO OF REPAIR DAYS:<br>BY: AUTHORIZED ON: |      |            |        | 50 100.00    |
| 2  | B  | BP-LAB2 CHECK WIRING AND CONDUCT LEAK TEST                                                                                                                                                     |      |            |        | 180.00       |
| 3  | B  | BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR                                                                                                                                                  |      |            |        | 180.00       |
| 4  | B  | BP-MECH2 RESET ECU                                                                                                                                                                             |      |            |        | 180.00       |
| 5  | B  | BP-LAB2 REPL ACC AFF PARTS AND PANEL<br>STRAIGHTEN AND REALIGN ACC AFF AREA @720                                                                                                               |      |            |        | 1440 2160.00 |
| 6  | B  | BP-RES2 RESSPRAY ACC AFF AREA @550                                                                                                                                                             |      |            |        | 1180 1770.00 |
| 7  | 1  | T52023-47030 REINFORCEMENT ? xsn                                                                                                                                                               | 1.00 | 336.30     |        | 336.30 X     |
| 8  | 2  | T52575-47040 RETAINER, RR BUMPER                                                                                                                                                               | 1.00 | 118.90     |        | 118.90       |
| 9  | 3  | T52159-47913 COVER, RR BUMPER                                                                                                                                                                  | 1.00 | 447.20     |        | 447.20       |
| 10 | 4  | T52169-47020 COVER, RR BUMPER                                                                                                                                                                  | 1.00 | 15.50      |        | 15.50        |
| 11 | 5  | T52453-47010 GUARD, RR BUMPER                                                                                                                                                                  | 1.00 | 582.20     |        | 582.20       |
| 12 | 6  | S52161-0K040 PIECE,RR BUMPER                                                                                                                                                                   | 1.00 | 4.10       |        | 53.30 4.10   |
| 13 | 7  | T52565-47900 FILLER, RR BUMPER                                                                                                                                                                 | 1.00 | 124.90     |        | 124.90       |
| 14 | 8  | T81581-47011 LENS & BODY, RR                                                                                                                                                                   | 1.00 | 506.70     |        | 506.70       |

| For & on behalf of                | Customer's Signature                  | Charge Summary                                           | Total                  |
|-----------------------------------|---------------------------------------|----------------------------------------------------------|------------------------|
| Borneo Motors (Singapore) Pte Ltd | Please acknowledge receipt of vehicle | Parts<br>Labour<br>Sublet<br>Lubrication/Fluid<br>Others | Less<br><br>Amount Due |

Company Copy



# Borneo Motors

infinite

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
No. 2 PANDAN CRESCENT  
SINGAPORE 128462, Tel no.: 6631 1188



# TOYOTA

## ESTIMATE

| Account Details   | Account No.                 | Customer Details                             |
|-------------------|-----------------------------|----------------------------------------------|
| THIRD PARTY CLAIM | S1000020 / TPCLAIM          | M/S Grab Rentals Pte Ltd                     |
|                   | Document No.<br>0           | 6 Battery Road<br>#38-04<br>Singapore 049909 |
|                   | Document Date<br>28/08/2021 | Work: 65703925                               |

| Year | Model  | Variant   | Reg. Date  | Reg. No. | Kilometers | Wip No. | Order No. / Remarks  |
|------|--------|-----------|------------|----------|------------|---------|----------------------|
| 2017 | ZVW50R | AHXEBW Q3 | 13/04/2017 | SLM8471K | 0          | 64351   | 66TP/SLM8471K/280821 |

| Chassis No.       | Engine No. | Terms | SA / Counter | Vehicle In | Collected On         |
|-------------------|------------|-------|--------------|------------|----------------------|
| JTDKB3FU803554660 | 2ZRS031607 | 60    | Shashitharan | --/--/---- | 0.00 --/--/---- 0.00 |

| L  | Cd | Job/Parts Description                           | Qty  | Unit Price | Disc % | Amount   |
|----|----|-------------------------------------------------|------|------------|--------|----------|
| 15 | 9  | T76801-47110 B0 GARNISH SUB-ASSY, <i>repair</i> | 1.00 | 937.60     |        | 937.60 X |
| 16 | 0  | T75403-48010 PLATE, LUGGAGE <i>new</i>          | 1.00 | 48.40      |        | 48.40 X  |
| 17 | 1  | T75441-47130 PLATE, LUGGAGE COMPT <i>new</i>    | 1.00 | 55.20      |        | 55.20 X  |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Repair*  
*Hy 90010068*  
*4 days*  
*30/08/21 @ 1510*  
*Reg before paint*

|                                                         |                                       |                                                                                           |                               |          |
|---------------------------------------------------------|---------------------------------------|-------------------------------------------------------------------------------------------|-------------------------------|----------|
| For & on behalf of<br>Borneo Motors (Singapore) Pte Ltd | Customer's Signature                  | Charge Summary                                                                            | Total                         | 7,747.00 |
|                                                         | Please acknowledge receipt of vehicle | Parts 3,177.00<br>Labour 4,570.00<br>Sublet 0.00<br>Lubrication/Fluid 0.00<br>Others 0.00 | GST 7.00% 542.29<br>Less 0.00 |          |
|                                                         |                                       |                                                                                           | Amount Due                    | 8,289.29 |

Company Copy