

Vin's

Vin's Motor Pte Ltd
 160 Sun Ming Drive
 #03-03 Sun Ming Arcade
 Singapore 575722
 Tel : 6453 2121 Fax : 6459 9795
 GST Registration No : 199906067G

Estimated Cost of Repair

Attention To : SMRT Corporation Ltd
 SMRT Corporation Ltd
 6 Ang Mo Kio Street 62
 Singapore 569140

Claim Details

Case Ref. No. : TP/082021/4962
Date : 30-08-2021

Vehicle Details

Make & Model : COROLLA ALTIS 1.6 CVT
Chassis No : MR053REH104554271
Registration No : SLF8906K

Third Party Vehicle Details

Registration No : SMB225D

S/N	Description	Qty	Unit Price	Discount	Amount (\$)
	RECOMMENDED PARTS				
1	REAR RH TAILLAMP ?	1.00	\$391.70	-25.00%	\$293.78
2	REAR BUMPER / TN	1.00	\$482.00	-25.00%	\$361.50
3	REAR BUMPER RH SIDE RETAINER cut	1.00	\$92.33	-25.00%	\$69.25
4	REAR BUMPER CLIPS / MC	10.00	\$3.50	-25.00%	\$26.25
5	REAR RH FENDER / Blue	1.00	\$939.20	-25.00%	\$704.40
6	REAR RH FENDER INNER SHIELD ?	1.00	\$39.70	-25.00%	\$29.78
7	FRONT FENDER INNER SHIELD CLIPS / MC	10.00	\$3.00	-25.00%	\$22.50
8	REAR RH WHEEL KNUCKLE ARM BEARING / Jm	1.00	\$637.00	-25.00%	\$477.75
9	REAR AXLE X NN (photo)	1.00	\$2,347.00	-25.00%	\$1,760.25
	SPECIAL NETT				
1	REAR WINDSCREEN GUM / MC	1.00	\$60.00		\$60.00
	RECOMMENDED LABOUR				
1	TO CHECK WHEEL ALIGNMENT	1.00	\$120.00		\$120.00
2	TO REMOVE AND REFIX REAR WINDSCREEN	1.00	\$180.00		\$180.00
3	TO REMOVE AND REFIX REAR UNDERCARRIAGE	1.00	\$380.00		\$380.00
4	TO REMOVE AND REFIX REAR SEAT CUSHION AND ROOF LINING	1.00	\$280.00		\$280.00
5	TO REPAIR REAR DAMAGES	1.00	\$680.00		\$680.00
6	TO SPRAY PAINTING	1.00	\$880.00		\$880.00

60
 120
 ?
 600
 550
 600

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Authority
Singapore 575711
Tel: 6453 2121 Fax: 6459 9795
GST Registration No: 199906067G

Payment Information:**Payment / Cheque to issue:**

Vin's Motor Pte Ltd

Bank - UOB Account: 451-307-638-4

Paynow UEN: 199906067G

Subtotal w/o GST:	\$6,325.48
GST (7%):	\$442.79
Subtotal:	\$6,768.24
Deposit:	
Balance Due:	\$6,768.24

Amount in words:

Six Thousand Seven Hundred Sixty Eight & Cents
Twenty Four Only.

6 & Days.

L/S

After repair photos.

Chen Q: ap

31/8/2021

LiK Auto Consultants hence notify**the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be re-surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Issued by Raymond Teo

This is a computer-generated document. No signature is required.



SLF8906K

Toyota (USA) : Corolla : 2014-19 : Sedan : with 215/45R17 Tire
4-Wheel Total Alignment

Front : Left

Actual	Before	Specified Range
-1°07'	-1°07'	-1°19' 0°11'
2°59'	2°59'	2°14' 3°44'
-0°08'	-0°08'	-0°06' 0°06'
13°06'	13°06'	
11°58'	11°58'	

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-1°00'	-1°00'	-1°19' 0°11'
3°05'	3°05'	2°14' 3°44'
0°15'	0°14'	-0°06' 0°06'
12°38'	12°38'	
11°38'	11°38'	

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°07'	-0°07'	-0°45' 0°45'
-0°06'	-0°06'	-0°45' 0°45'
0°28'	0°28'	
0°07'	0°06'	-0°12' 0°12'

Rear : Left

Actual	Before	Specified Range
-1°48'	-1°48'	-1°58' -0°58'
0°16'	0°16'	0°01' 0°18'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-2°46'	-2°46'	-1°58' -0°58'
-0°18'	-0°18'	0°01' 0°18'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
0°57'	0°58'	-0°45' 0°45'
-0°02'	-0°02'	0°02' 0°36'
0°17'	0°17'	