

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047

Tel: 6484 1626 (24Hrs) Fax: 6484 0465

Business Reg No: 221880/00C GST Reg. No: MX-0486007-A0

India International Insurance Pte Ltd

- To: _____
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final survey company

Acknowledged by Repairer

Signature: _____
Date: _____
Specialised in Car Painting, Welding,
Panel Beating and Insurance Claim.

ESTIMATE

Third Party

Policy No: _____

22.09.2021

Date: _____

2017

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "BMW X1" Reg. No. SJY5488T Claiming Against Your Insured Veh. No. SLJ5273B			
1pc	Tailgate Emblem		77.50 ✓ 77.50 NECV
1pc	Rear Bumper		990.00 BTV
14pcs	Rear Bumper Clips	3.90	30.00 ✓ 54.60 NECV
2pcs	Rear Bumper Brackets	175.00	350.00 ? NSX
1pc	Rear Bumper Sponge		180.00 ? NSX
1pc	Rear Bumper Reinforcement		545.00 ? BTV
1pc	Rear Bumper Inner Core		194.00 ? NSX
2pcs	Rear Bumper Lower Retainers	125.00	✓ 250.00 ? BRV
1pc	Rear Bumper Center Cover		250.00 BRV
4pcs	Rear Bumper Reverse Sensor Holder	25.00	126.50 ✓ 100.00 NECV
1pc	Rear Bumper Lower Diffuser Cover		189.40 ✓ 238.00 DPV
1pc	Rear Bumper Lower Diffuser Cover Center Garnish Cover		✓ 125.00 ? BRV
1pc	Rear Bumper Tow Point Cover		✓ 40.00 UTV
1pc	Rear Bumper Inner Boot Sensor Strip		✓ 50.00 ? DDV
1pc	Rear Bumper Inner Boot Sensor Antenna		✓ 55.00 ? TNV
1pc	Rear Bumper Inner Boot Sensor Module		✓ 532.00 ? BRV
1pc	Rear Bumper Inner Boot Sensor Module Housing		✓ 51.00 ? UTV
1pc	Rear Exhaust Silencer Heat Shield		105.00 ✓ 340.00 ? DDV
	Less 10%		4,422.10
			442.21
			3,979.89
	Tailgate Badge "Turbo"		✓ 80.00 SN NECV
	Tailgate Sticker		50.00 ✓ 120.00 SN NECV
	Tailgate Badge X1 (Black Edition)		58.35 ✓ 120.00 SN NECV
	Rear Bumper Top Carbon Sticker		58.00 ✓ 180.00 SN NECV
	Rear Bumper Top Performance Sticker		✓ 150.00 SN NECV
	Rear Bumper Reverse Sensor		✓ 250.00 SN ? BR
	To Conduct Electrical Check, Replace Reverse Sensors, Reprogram System		✓ 60.00 ✓ 120.00 ? NECV
	To Repair Rear Exhaust Silencer & Tip		60.00 ? NDX
	Labour Charge - Panel Beating, Repairing Rear Tailgate, End Panel And Parts Replacement		700.00 ? 500.00 ✓
	To Spray Paint Affected Areas (2k - 3 Tone)		800.00 ✓ 600.00
			6,559.89
		Total :	

Survey
23/9/2021
1510 hrs

TC Lim
42361577
1445 TC Lim

Resurveyed
24/9/2021
1445 TC Lim

Total :

Lump sum repair
Repair days 4

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Lump sum repair
Repair days 4

Parts	2939.76
SN	638.35
Labour	1160.00
	4,738.11
@ 20%	947.62
	3790.49

LS 3,800.00

Trini

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

NV 41,271/2