Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd

Est. Duration of Repair

: 4

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Adeline Chng Pei Wen Date: 31 Aug 2021

Preliminary Advice

Insured Vehicle No : SLL5498J

TP Vehicle No : SLH1545D : 20/08/2021 Accident Date Make : TOYOTA COROLLA Assignment Date : 31/08/2021

Date of Inspection : 31/08/2021

Inspection At : ETHOZ GROUP LTD (HQ)

30 BUKIT BATOK CRESCENT

SINGAPORE 658075

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,411.50
Revised Amount	:S\$	2,461.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,461.50

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$ Pre-Accident Value :S\$ COE / PARF Rebate :S\$ Salvage Value :S\$ Margin for Repair :S\$

Remarks

)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kind	dly
	let us have your authorisation.	

(The vehicle is uneconomical	≀to l	be repaired	. vou are advise	ď	to invite	e tend	ler f	or t	he wrec	:k
١	. ,			bo ropanoa	, you alo aavioo	ч		COLIC		01 1	110 11100	

Other comments: Please note that the preliminary advice amount (Revised) stated are subject to consistency (X) check, part prices and labour cost.