

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 2017S

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|---------------|-------------------------------|----------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | FRONT BUMPER (CONSISTENT) | DEFORMED | 563.10 | 563.10 |
| 1 | FRONT BUMPER SIDE HOLDER RH (CONSISTENT) | DAMAGED | 38.40 | 38.40 |
| 1 | HEADLAMP RH (CONSISTENT) | CRACKED | 1,029.70 | 1,029.70 |
| 1 | FRONT RH FENDER (CONSISTENT) | DENTED | 480.30 | 480.30 |
| 1 | FRONT RH FENDER INNER SHIELD (CONSISTENT) | DEFORMED | 204.10 | 204.10 |
| 1 | FRONT RH SHOCK ABSORBER (CONSISTENT) | NOT NECESSARY | 575.90 | - |
| 1 | FRONT RH LOWER ARM (CONSISTENT) | NOT NECESSARY | 489.50 | - |
| 1 | FRONT RH KNUCKLE ARM (CONSISTENT) | NOT NECESSARY | 497.90 | - |
| 1 | FRONT RH WHEEL HUB C/W BEARING (CONSISTENT) | DAMAGED | 237.40 | 237.40 |
| | LESS 25% DISCOUNT | | - | -638.25 |
| | | | 4,116.30 | 1,914.75 |
| | SPECIAL NETT ITEMS | | | |
| 1 | FRONT BUMPER CLIPS (SN) (CONSISTENT) | NECESSARY | 30.00 | 30.00 |
| 1 | FRONT RH FENDER INNER SHIELD CLIPS (SN) (CONSISTENT) | NECESSARY | 30.00 | 30.00 |
| 1 | FRONT RH WHEEL RIM (SN) (CONSISTENT) | CUT | 680.00 | 500.00 |
| 1 | FRONT RH TYRE (SN) (CONSISTENT) | NOT NECESSARY | 280.00 | - |
| | | | 1,020.00 | 560.00 |
| | <u>LABOUR</u> | | | |
| | PANEL BEATING. | | 600.00 | 450.00 |
| | SPRAY PAINTING. | | 600.00 | 400.00 |
| | WIRING. | | 50.00 | 30.00 |
| | TO SPRAY TUFF COAT. | | 100.00 | 30.00 |
| | TO DISMANTLE UNDERCARRIAGE. | | 280.00 | 100.00 |
| | TO PERFORM WHEEL ALIGNMENT. | | 150.00 | 80.00 |
| | | | 1,780.00 | 1,090.00 |
| | GRAND TOTAL | | 6,916.30 | 3,564.75 |

Report Ref No. CC4/ASM21009131/Apa3q2



Page No.:2 of 2

| RECOMMENDED COST OF LUMP SUM REPAIRS | | 2,800.00 |
|--------------------------------------|--|----------|
| (TO ITS PRE-ACCIDENT CONDITION) | | |

Report Ref No. CC4/ASM21009131/Apa3q2



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.