



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:YVONNE		Ref: CC4/ASM21009131/Apa3q2 Date: 17/04/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 8635E	Veh. Inspected	SLA 2017S
Policy No.	P2419138	Coverage (\$)	0.00
Claim No.	S1M03G4N	Excess (\$)	0.00
Assign From		Assign Date	31/08/2021
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA FIELDER	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	NRE1618001067	Colour	BLUE
Odometer	177760 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/60 R15	HABILEAD	6 mm
L/H Front Tyre	195/60 R15	HABILEAD	6 mm
R/H Rear Tyre	195/60 R15	HABILEAD	6 mm
L/H Rear Tyre	195/60 R15	HABILEAD	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY & UNDERCARRIAGE. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	19/08/2021	Inspection Date	31/08/2021
Survey held at	ACE AUTOLUTION PTE LTD 13 KAKI BUKIT ROAD 4 #03-29 BARTLEY BIZ CENTRE SINGAPORE 417807		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	