

(05/11/13) wef
ASS. REC. BY: Marcus

REF:

CS/MSG 21009133/UTF3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGA 5984D

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SGA 5984D

Yr Regn:

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The vehicle system damaged or
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Fit windscreen cracked, rooftop, ffr, n/s body, rear, o/s body the
wreag sticker cause of Damage Due to concrete debris

coe int. 1 13-12-2022 NTA \$5486

TOTAL 9 panel, Bonnet, ffr LH fender, ffr door LH, Rear door LH, Rear fender, LH pillar
Boot lid, Rear bumper, Rear fender RH, Roof panel, door mirror

fr owner agree Not to replace wreag sticker

P/P \$ 3334.00 cost plus 20% confirmed with David

red:3791.60;53%

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3033/08/21

Your Ref:

Date: 31st AUG 2021

MR KOU SHONG LIM
BLK 109, #07-712
SIMBI STREET 1
SINGAPORE 520109

cost plus 20%

Estimate cost of repair to MITSUBISHI LANCER 1.5 (A) saloon - SJA 5984 D

1 pc front windscreen glass	CRa	480	\$ 987.00 N	✓
1 pc front windscreen glass outer moulding	cut	60	137.00 N	✓
1 pc front windscreen glass damper	AA		60.00 N	X
20 pcs roof moulding clips	AA		110.00 N	X
1 pc p/s tail lamp assy	CRa	11C	332.00 N	X
8 pcs rear bumper clips	AA		28.00 N	X

Less 10% \$ 165.40

\$ 1,488.60

1 pc front windscreen glass sealant	neu	40	45.00 S.N	40
1 pc front windscreen glass BRP bracket sticker	neu		12.00 S.N	✓
1 pc front windscreen glass solafilm	AA		350.00 S.N	X
1 set body sticker	wave refer to spray painting		2,400.00 S.N	X

\$ 2,807.00 S.N

To remove & refix front windscreen glass & necessary parts. 150.00 120

To remove & refix roof moulding, upholstery, lining, garnish rear n/s door trim board cover, front bonnet insulator & necessary parts, to enable repair roof panel, door pillar, rear n/s door, front bonnet & necessary parts. 280.00 150

To wiring check up for affected wiring system. 50.00 X

Labour charge to remove & cut out necessary parts, to jack, straighten & knocking out roof panel, door pillar panel, rear bumper, rear n/s door, front bonnet & necessary parts. to weld, renew & align above parts. 900.00 800

To putty & respray painting on all affected accident parts. 1,500.00 1400

Labour charge to remove & refix body sticker & necessary. 350.00 200

\$ 7,125.60

=====

Dollars : Seven Thousand One Hundred Twenty Five And Cents Sixty Only.

HUP MOTOR TRADING & SERVICE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

cost

\$ 510

20%

P. 612

SN - 52

L - 2670

3334