

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0695/2021/ZK
DATE : 26-Aug-21
WIP : 41362

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 30/6/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR MANKUDE BHASKER RAO RAVI KIRAN
ADDRESS : 130 TANJONG RHU ROAD
#13-09
SINGAPORE 436918
TELEPHONE : HP +65 8332 2043
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210042163
VEHICLE NO : **SNA 3118 D**
MODEL CODE : AUDI Q7 2.0 TFSI
MODEL YEAR : 29/4/2021
ENGINE NO : CYR 103337
CHASSIS NO : WAUZZZ4M0MD008609
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 25-Aug-21
PLACE OF ACCIDENT : PEBBLE BAY PARKING GARAGE LOBBY M

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED FRONT LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 3118 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE , CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS.HORNS.OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓ ✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE	S/N \$ 900.00	✓ 250 ✓
3	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 450.00	X
4	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET,BOTH FRONT FENDERS,RHS FRONT DOOR AND BOTH HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.	\$ 5,400.00	3x600=1800 ✓
5	TO RESPRAY FRONT BUMPER , BOTH FRONT BUMPER LOWER SPOILERS,BONNET , BOTH FRONT FENDERS,RHS FRONT DOOR , RHS REAR DOOR,LHS REAR DOOR , TWO DOOR COVERS AND BOTH FRONT & REAR WHEEL ARCH TRIMS	\$ 9,000.00	5150 ✓ 6x600 = 3600 Bumper Spoiler = 250 2 Door Cover = 250 x 2 = 500 4 Wheel Arch = 4x200 = 800
SUB TOTAL LABOUR CHARGES (FRONT)		\$ 16,230.00	5150

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED REAR LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 3118 D

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID KICK SENSOR. CHECK FUNCTION	S/N \$	360.00	✓✓
2	TO RENEW LHS 1/4 GLASS TO FACILLITATE FENDER RENEWAL	S/N \$	300.00	✓✓
3	TO INSTALL SOLAR FILM FOR LHS SIDE 1/4 GLASS	S/N \$	400.00	✓✓
4	TO CARRY OUT WATER SEEPAGE TEST ON 1/4 GLASS	S/N \$	200.00 150	✓
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHT, BATTERY MANAGER, FUSE AND RELAY TRAYS.ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,400.00	✓✓
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST. HAT TRAY,ABCD PILLAR TRIMS,LUGGAGE COMPARTMENTS TRIMS.DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,400.00	✓✓
SUB TOTAL LABOUR CHARGES (REAR)		:	\$ 4,060.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED REAR LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 3118 D

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO SET UP AND PLACE VEHICLE IN ALUMINIUM BAY	S/N \$	1,800.00	✓ ✓
8	TO DISMANTLE AND RENEW REAR BUMPER.TO CUT OUT AND WELD LHS REAR FENDER.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.	\$	6,300.00	600x6 = 3600 4800 3600
9	TO RESPRAY REAR UPPER BUMPER, REAR LOWER BUMPER, LHS FENDER, LHS SILL PANEL, DRAIN CHANNEL, ROOF CHANNEL, DOOR ENTRANCE AND REAR END PANELLING.	\$	6,500.00	3300 ✓ Fender = 3.5 x 600 = 2100 Bumper x 2 = 600 x 2 = 1200
10	TO CARRY OUT ALUMINIUM PRIMER WORKS	S/N \$	900.00	✓ ✓
11	TO RENEW ALL RIMS AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	400.00	✓ ✓
12	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	S/N \$	384.00	✓ ✓
TOTAL LABOUR CHARGES		:	<u>\$ 36,574.00</u>	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

FRONT MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 3118 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Dehd</i>	1	\$ 2,724.00	✓ 2179.20
2	FRONT BUMPER FIXING PARTS <i>xeu</i>	1	\$ 696.00	+
3	FRONT TOWING EYE COVER <i>xeu</i>	1	\$ 39.00	+
4	FRONT BUMPER AIR GUIDE - LH <i>xt-?</i>	1	\$ 67.00	✓ 52.96
5	FRONT BUMPER COVER CAP - LH <i>xeu</i>	1	\$ 36.00	+
6	FRONT BUMPER CLOSING ELEMENT - UPPER CENTER <i>xeu</i>	1	\$ 277.00	✓ 221.20
7	FRONT BUMPER LOCKING CLIP <i>xeu</i>	6	\$ 24.00	+
8	FRONT BUMPER GRILLE <i>Dehd</i>	1	\$ 206.00	✓ 164.40
9	FRONT BUMPER SILVER UNDERRUN BAR <i>Dehd</i>	1	\$ 583.00	✓ 466.40
10	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>?</i>	1	\$ 210.00	✓ 167.60
11	FRONT BUMPER SPOILER - LH / RH <i>LH Dehd</i>	2	\$ 422.00	✓ 211 168.80
12	FRONT BUMPER SPOILER - OUTER LH / RH <i>LH Dehd</i>	2	\$ 88.00	✓ 44 34.72
13	FRONT BUMPER TRIM - LH / RH <i>LH Dax</i>	2	\$ 26.00	✓ 13 9.68
14	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>LHut</i>	2	\$ 204.00	✓ 102 81.60
15	FRONT BUMPER AIR GUIDE GRILLE END CAP - LH / RH <i>?</i>	2	\$ 96.00	✓ 38.16
16	AIR GUIDE GRILLE INSERT - LH <i>?</i>	2	\$ 102.00	✓ 41.20
17	FRONT RADIATOR GRILLE <i>cruld</i>	1	\$ 2,473.00	✓ 1978.40
18	FRONT RADIATOR INNER COVER <i>xeu</i>	1	\$ 72.00	+
19	FRONT CAMERA COVER <i>xeu</i>	1	\$ 13.00	+
20	FRONT BUMPER SPOILER - INNER LH / RH <i>?</i>	2	\$ 118.00	✓ X
SUB TOTAL SPARE PARTS (FRONT)		:	\$ 8,476.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

FRONT MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 3118 D

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT		REMARKS	
21	FRONT BUMPER REINFORCEMENT FOAM ?	1	\$	171.00	?	136.80
22	FRONT BUMPER CARRIER ?	1	\$	964.00	?	771.20
23	FRONT BUMPER GUIDE SECTION - LH ?	1	\$	44.00	?	34.88
24	FRONT BUMPER TOP COVER <i>Not m</i>	1	\$	131.00	X	
25	CAUTION STICKER <i>Not m</i>	1	\$	14.00	X	
26	AIR-CONDITIONER STICKER	1	\$	8.00	X	
27	HORN - LH / RH ?	2	\$	452.00	?	X
28	FRONT PARKING AID SENSOR <i>Not m</i>	2		TBC	X	
29	FRONT PARKING AID SENSOR SEAL <i>Not m</i>	4	\$	14.00	X	
30	FRONT FENDER - LH / RH <i>LH Repair RH Dented</i>	1	\$	3,240.00	1620	1296
31	FRONT FENDER ATTACHMENT PART <i>Not m</i>	1	\$	117.00	X	
32	FRONT FENDER BRACE - LH ?	1	\$	101.00	?	X
33	FRONT FENDER BRACKET - LH ?	1	\$	65.00	?	X
34	FRONT FENDER CLOSING ELEMENT - RH ?	1	\$	33.00	?	X
35	WHEEL HOUSING LINER - FRONT LH <i>Not m</i>	1	\$	240.00	X	
36	WHEEL HOUSING LINER - REAR LH	1	\$	240.00	X	
37	FRONT BONNET <i>Repair</i>	1	\$	6,672.00	X	
38	FRONT BONNET ATTACHMENT PARTS <i>Repair</i>	1	\$	224.00	X	
39	FRONT BONNET IMPACT PROTECTION	1	\$	107.00	X	
40	FRONT BONNET STRIKER - LH <i>Not m</i>	1	\$	117.00	X	
SUB TOTAL SPARE PARTS (FRONT)		:	\$	12,954.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

FRONT MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 3118 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT BONNET LOCK WITH MICRO-SWITCH <i>Ne m</i>	1	\$ 213.00	<i>X</i>
42	FRONT HEADLIGHT MOUNTING - LH / RH ?	2	\$ 236.00	? <i>94.40</i>
43	FRONT HEADLIGHT <i>LH cracked</i>	2	\$ 17,248.00	<i>8624</i> 6924
44	FRONT HEADLIGHT HOSE - LH <i>Ne n</i>	1	\$ 39.00	<i>X</i>
45	FRONT HEADLIGHT LIFT CYLINDER - LH ?	1	\$ 198.00	? <i>158.40</i>
46	FRONT HEADLIGHT WASHER HOSE <i>Ne n</i>	1	\$ 121.00	<i>X</i>
47	FRONT BUMPER AIR GUIDE - LH / RH / UPPER / LOWER ?	6	\$ 200.00	? <i>X</i>
48	FRONT AIR SENSOR BRACKET <i>Ne n</i>	1	\$ 5.00	<i>X</i> <i>3.36</i>
49	FRONT WHEEL COVER - LH / RH <i>Ne n</i>	2	\$ 1,112.00	<i>889.60</i>
50	FRONT DOOR - RH <i>Dented.</i>	1	\$ 5,087.00	<i>4069.60</i>
51	FRONT DOOR SEAL <i>Ne n</i>	1	\$ 253.00	<i>202</i>
52	FRONT DOOR BONDING AGENT ?	1	\$ 49.00	? <i>X</i>
53	FRONT DOOR CLEANING SOULTION ?	1	\$ 68.00	? <i>X</i>
54	FRONT DOOR APPLICATOR ?	1	\$ 8.00	? <i>X</i>
55	FRONT DOOR GROMMET ?	8	\$ 21.00	? <i>X</i>
56	FRONT DOOR ATTACHMENT PART <i>Ne n</i>	1	\$ 352.00	<i>X</i>
57	FRONT DOOR CATCH - RH ?	1	\$ 128.00	? <i>X</i>
58	FRONT DOOR COVER - RH <i>Ne n</i>	1	\$ 858.00	<i>686.40</i>
59	TYER PRESSURE STICKER <i>Ne n</i>	1	\$ 42.00	<i>X</i>
SUB TOTAL SPARE PARTS (FRONT)		:	\$ 26,238.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

REAR MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 3118 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
60	REAR DOOR COVER ?	1	\$ 785.00	? X
61	WHEEL ARCH DOOR - LH / RH <i>new</i>	2	\$ 382.00	✓ 304.80
62	REAR BUMPER - UPPER <i>behind</i>	1	\$ 1,362.00	✓ 1089.60
63	REAR BUMPER - LOWER <i>Regis</i>	1	\$ 1,841.00	X 1472.80
64	RAER BUMPER FIXING PARTS <i>new</i>	1	\$ 439.00	+
65	REAR BUMPER SPOLIER <i>new</i>	1	\$ 1,259.00	✓ 1007.20
66	REAR BUMPER CARRIER <i>new</i>	1	\$ 1,417.00	+
67	REAR BUMPER SEAL - LH / RH <i>new</i>	1	\$ 14.00	+
68	RAER BUMPER HOLDING STRIP <i>new</i>	1	\$ 182.00	+
69	REAR BUMPER GUIDE SECTION - CENTER <i>new</i>	1	\$ 142.00	+
70	REAR BUMPER GUIDE SECTION - LH ?	1	\$ 63.00	50.32
71	REAR TAIL LIGHT BULB - LH <i>new</i>	1	\$ 359.00	+
72	REAR WHEEL COVER - LH / RH <i>new</i>	2	\$ 730.00	✓ 584
73	REAR QUARTER SIDE FENDER - LH <i>Dented</i>	1	\$ 7,217.00	✓ 5773.60
74	REAR QUARTER GLASS - LH <i>new</i>	1	\$ 946.00	✓ 756.80
75	ALUMINIUM POWDER ?	1	\$ 573.00	✓ 458.40
76	HARDENER	1	\$ 210.00	✓ 168
77	ALUMINIUM PRIMER	1	\$ 212.00	✓ 169.60
78	CLEANING BLOCK	1	\$ 77.00	✓ X
79	EPOXY ADHESIVE	1	\$ 113.00	✓ 90.40
SUB TOTAL SPARE PARTS (REAR)		:	\$ 18,323.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NOBA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

REAR MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 3118 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
80	STATIC MIXER <i>new</i>	1	\$ 8.00	✓ 5.84
81	ALUMINIUM RIM <i>Front LH, Rear LH, Front RH</i>	4	\$ 8,456.00	✓ 6342 5349.60
82	REAR WHEEL SPOILER - LH <i>Front a</i>	1	\$ 36.00	+
83	REAR SILL TRIM STRIP - LH	1	\$ 165.00	+
84	REAR WHEEL HOUSING LINER - LH <i>not new</i>	1	\$ 320.00	+
85	FRONT NO PLATE <i>new</i>	S/N	\$ 60.00	✓ 60
86	GLASS SEALANT <i>new</i>	1	\$ 100.00	✓ 100
87	ARCrylic SEALANT <i>2</i>	1	\$ 180.00	✓ 180
88	CRAVITY WAX <i>new</i>	1	\$ 140.00	✓ 140
89	STONE CHIP	1	\$ 180.00	✓ 180
90	SUNDRIES <i>?</i>		\$ 500.00	? 81.28
TOTAL SPARE PARTS (FRONT + REAR)		:	\$ 76,136.00	
TOTAL LABOUR CHARGES		:	\$ 36,574.00	
GRAND TOTAL		:	\$ 112,710.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian*
 SURVEYED DATE : *30/08/01*
 AUTHORISED DATE :
 EXCESS COST :
 LIABILITY :
 REMARKS : *Not Authorised, 22 Days. Rear: 14 Days*
Front: 5 Days
Bonnet, Door R/W = 2 Days.
Wheel Alignment = 1 Day
and R/W
22 Days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: