

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0695/2021/ZK
DATE : 26-Aug-21
WIP : 41362

Veron

\$63551.92

28 Days.

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 30/6/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR MANKUDE BHASKER RAO RAVI KIRAN
ADDRESS : 130 TANJONG RHU ROAD
#13-09
SINGAPORE 436918
TELEPHONE : HP +65 8332 2043
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210042163
VEHICLE NO : SNA 3118 D
MODEL CODE : AUDI Q7 2.0 TFSI
MODEL YEAR : 29/4/2021
ENGINE NO : CYR 103337
CHASSIS NO : WAUZZZ4M0MD008609
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 25-Aug-21
PLACE OF ACCIDENT : PEBBLE BAY PARKING GARAGE LOBBY M

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED FRONT LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 3118 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE	S/N \$ 900.00	250 ✓ 300
3	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 450.00	X
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS, RHS FRONT DOOR AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,400.00	3x600=1800 ✓
5	TO RESPRAY FRONT BUMPER, BOTH FRONT BUMPER LOWER SPOILERS, BONNET, BOTH FRONT FENDERS, RHS FRONT DOOR, RHS REAR DOOR, LHS REAR DOOR, TWO DOOR COVERS AND BOTH FRONT & REAR WHEEL ARCH TRIMS	\$ 9,000.00	5150 ✓ 6x600 = 3600 Bumper Spoiler = 250 2 Door Cover = 250 x 2 = 500
SUB TOTAL LABOUR CHARGES (FRONT)		\$ 16,230.00	4 wheel Ar = 4x200 = 800

5150

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED REAR LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 3118 D

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID KICK SENSOR. CHECK FUNCTION	S/N \$	360.00	✓✓
2	TO RENEW LHS 1/4 GLASS TO FACILLITATE FENDER RENEWAL	S/N \$	300.00	✓✓
3	TO INSTALL SOLAR FILM FOR LHS SIDE 1/4 GLASS	S/N \$	400.00	✓✓
4	TO CARRY OUT WATER SEEPAGE TEST ON 1/4 GLASS	S/N \$	200.00	150✓
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHT, BATTERY MANAGER, FUSE AND RELAY TRAYS. ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,400.00	✓✓
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST. HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENTS TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,400.00	✓✓
SUB TOTAL LABOUR CHARGES (REAR)		:	<u>\$ 4,060.00</u>	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED REAR LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 3118 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO SET UP AND PLACE VEHICLE IN ALUMINIUM BAY	S/N \$ 1,800.00	✓ ✓
8	TO DISMANTLE AND RENEW REAR BUMPER. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.	\$ 6,300.00	✓ ✓
9	TO RESPRAY REAR UPPER BUMPER, REAR LOWER BUMPER, LHS FENDER, LHS SILL PANEL, DRAIN CHANNEL, ROOF CHANNEL, DOOR ENTRANCE AND REAR END PANELLING.	\$ 6,500.00	✓ ✓
10	TO CARRY OUT ALUMINIUM PRIMER WORKS	S/N \$ 900.00	✓ ✓
11	TO RENEW ALL RIMS AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 400.00	✓ ✓
12	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	S/N \$ 384.00	✓ ✓
TOTAL LABOUR CHARGES		\$ 36,574.00	

$600 \times 8 = 4800$
 $600 \times 6 = 3600$
 4800
 3600
 $Fender = 3.5 \times 600 = 2100$
 $Bumper \times 2 = 600 \times 2 = 1200$



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

FRONT MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 3118 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Dehd</i>	1	\$ 2,724.00	✓ 2179.20
2	FRONT BUMPER FIXING PARTS <i>Neu</i>	1	\$ 696.00	x
3	FRONT TOWING EYE COVER <i>Neu</i>	1	\$ 39.00	x
4	FRONT BUMPER AIR GUIDE - LH <i>ext Dehd.</i>	1	\$ 67.00	✓ 52.96
5	FRONT BUMPER COVER CAP - LH <i>Neu</i>	1	\$ 36.00	x
6	FRONT BUMPER CLOSING ELEMENT - UPPER CENTER <i>cracked.</i>	1	\$ 277.00	✓ 221.20
7	FRONT BUMPER LOCKING CLIP <i>Neu</i>	6	\$ 24.00	x
8	FRONT BUMPER GRILLE <i>Dehd</i>	1	\$ 206.00	✓ 164.40
9	FRONT BUMPER SILVER UNDERRUN BAR <i>Dehd</i>	1	\$ 583.00	✓ 466.40
10	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>cracked.</i>	1	\$ 210.00	✓ 167.60
11	FRONT BUMPER SPOILER - LH / RH <i>LH Dehd</i>	2	\$ 422.00	211 168.80
12	FRONT BUMPER SPOILER - OUTER LH / RH <i>LH Dehd</i>	2	\$ 88.00	44 34.72
13	FRONT BUMPER TRIM - LH / RH <i>LH Dehd</i>	2	\$ 26.00	13 9.68
14	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>LH Dehd</i>	2	\$ 204.00	102 81.60
15	FRONT BUMPER AIR GUIDE GRILLE END CAP - LH / RH <i>LH Dehd</i>	\$	96.00	38.16
16	AIR GUIDE GRILLE INSERT - LH <i>Dehd.</i>	2	\$ 102.00	41.20
17	FRONT RADIATOR GRILLE <i>cracked</i>	1	\$ 2,473.00	✓ 1978.40
18	FRONT RADIATOR INNER COVER <i>Neu</i>	1	\$ 72.00	x
19	FRONT CAMERA COVER <i>Neu</i>	1	\$ 13.00	x
20	FRONT BUMPER SPOILER - INNER LH / RH <i>Not Nec.</i>	2	\$ 118.00	7 x
SUB TOTAL SPARE PARTS (FRONT)		:	\$ 8,476.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

FRONT MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 3118 D

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	FRONT BUMPER REINFORCEMENT FOAM <i>cracked</i>	1	S	171.00	? 136.80
22	FRONT BUMPER CARRIER <i>Dented</i>	1	S	964.00	? 771.20
23	FRONT BUMPER GUIDE SECTION - LH <i>cracked</i>	1	S	44.00	? 34.88
24	FRONT BUMPER TOP COVER <i>Not m</i>	1	S	131.00	X
25	CAUTION STICKER <i>Not m</i>	1	S	14.00	X
26	AIR-CONDITIONER STICKER <i>Not m</i>	1	S	8.00	X
27	HORN - LH / RH <i>Not Nec.</i>	2	S	452.00	? X
28	FRONT PARKING AID SENSOR <i>Not m</i>	2		TBC	X
29	FRONT PARKING AID SENSOR SEAL <i>Not m</i>	4	S	14.00	X
30	FRONT FENDER - LH / RH <i>LH Regis, RH Dented</i>	1	S	3,240.00	1620 1296
31	FRONT FENDER ATTACHMENT PART <i>Not m</i>	1	S	117.00	X
32	FRONT FENDER BRACE - LH <i>Not m</i>	1	S	101.00	? X
33	FRONT FENDER BRACKET - LH <i>Not m</i>	1	S	65.00	? X
34	FRONT FENDER CLOSING ELEMENT - RH <i>Not m</i>	1	S	33.00	? X
35	WHEEL HOUSING LINER - FRONT LH <i>Not m</i>	1	S	240.00	X
36	WHEEL HOUSING LINER - REAR LH <i>Not m</i>	1	S	240.00	X
37	FRONT BONNET <i>Regis</i>	1	S	6,672.00	X
38	FRONT BONNET ATTACHMENT PARTS <i>Not m</i>	1	S	224.00	X
39	FRONT BONNET IMPACT PROTECTION	1	S	107.00	X
40	FRONT BONNET STRIKER - LH <i>Not m</i>	1	S	117.00	X
SUB TOTAL SPARE PARTS (FRONT)		:	\$	12,954.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

FRONT MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 3118 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT BONNET LOCK WITH MICRO-SWITCH <i>Ne m</i>	1	\$ 213.00	X
42	FRONT HEADLIGHT MOUNTING - LH / RH <i>2H cracked</i>	2	\$ 236.00	? 94.40
43	FRONT HEADLIGHT <i>LH cracked</i>	2	\$ 17,248.00	8624 6924
44	FRONT HEADLIGHT HOSE - LH <i>Ne m</i>	1	\$ 39.00	X
45	FRONT HEADLIGHT LIFT CYLINDER - LH <i>cracked.</i>	1	\$ 198.00	? 158.40
46	FRONT HEADLIGHT WASHER HOSE <i>Ne m</i>	1	\$ 121.00	X
47	FRONT BUMPER AIR GUIDE - LH / RH / UPPER / LOWER <i>Ne m</i>	6	\$ 200.00	? X
48	FRONT AIR SENSOR BRACKET <i>Ne m</i>	1	\$ 5.00	X 3.36
49	FRONT WHEEL COVER - LH / RH <i>Ne m</i>	2	\$ 1,112.00	889.60
50	FRONT DOOR - RH <i>Dented.</i>	1	\$ 5,087.00	4069.60
51	FRONT DOOR SEAL <i>Ne m</i>	1	\$ 253.00	202
52	FRONT DOOR BONDING AGENT <i>Ne m</i>	1	\$ 49.00	? X
53	FRONT DOOR CLEANING SOLUTION <i>Ne m</i>	1	\$ 68.00	? X
54	FRONT DOOR APPLICATOR <i>Ne m</i>	1	\$ 8.00	? X
55	FRONT DOOR GROMMET <i>Ne m</i>	8	\$ 21.00	? X
56	FRONT DOOR ATTACHMENT PART <i>Ne m</i>	1	\$ 352.00	X
57	FRONT DOOR CATCH - RH <i>Ne m</i>	1	\$ 128.00	? X
58	FRONT DOOR COVER - RH <i>Ne m</i>	1	\$ 858.00	686.40
59	TYER PRESSURE STICKER <i>Ne m</i>	1	\$ 42.00	X
SUB TOTAL SPARE PARTS (FRONT)		:	\$ 26,238.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

REAR MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 3118 D

S/N	PARTS DESCRIPTION	QTY		DAMAGED PARTS & PRICES	
				S/NETT	REMARKS
60	REAR DOOR COVER <i>Not Rec</i>	1	S	785.00	? X
61	WHEEL ARCH DOOR - LH / RH <i>Rec</i>	2	S	382.00	✓ 304.80
62	REAR BUMPER - UPPER <i>Rehnd</i>	1	S	1,362.00	✓ 1089.60
63	REAR BUMPER - LOWER <i>torn</i>	1	S	1,841.00	X 1472.80
64	REAR BUMPER FIXING PARTS <i>Rec</i>	1	S	439.00	+
65	REAR BUMPER SPOILER <i>torn</i>	1	S	1,259.00	X 1007.20
66	REAR BUMPER CARRIER <i>Rec</i>	1	S	1,417.00	X
67	REAR BUMPER SEAL - LH / RH <i>Rec</i>	1	S	14.00	+
68	REAR BUMPER HOLDING STRIP <i>Rec</i>	1	S	182.00	+
69	REAR BUMPER GUIDE SECTION - CENTER <i>Rec</i>	1	S	142.00	+
70	REAR BUMPER GUIDE SECTION - LH <i>Cracked</i>	1	S	63.00	50.32
71	REAR TAIL LIGHT BULB - LH <i>Rec</i>	1	S	359.00	+
72	REAR WHEEL COVER - LH / RH <i>Rec</i>	2	S	730.00	✓ 584
73	REAR QUARTER SIDE FENDER - LH <i>Dented</i>	1	S	7,217.00	✓ 5773.60
74	REAR QUARTER GLASS - LH <i>Rec</i>	1	S	946.00	✓ 756.80
75	ALUMINIUM POWDER	1	S	573.00	✓ 458.40
76	HARDENER	1	S	210.00	✓ 168
77	ALUMINIUM PRIMER	1	S	212.00	✓ 169.60
78	CLEANING BLOCK <i>Not Rec</i>	1	S	77.00	X
79	EPOXY ADHESIVE <i>Rec</i>	1	S	113.00	✓ 90.40
SUB TOTAL SPARE PARTS (REAR)		:	\$	18,323.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

REAR MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 3118 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
80	STATIC MIXER <i>Nec</i>	1	\$ 8.00	✓ 5.84
81	ALUMINIUM RIM <i>81 Front LH, Rear LH, Front RH</i>	4	\$ 8,456.00	6342 5349.60
82	REAR WHEEL SPOILER - LH <i>Front RH</i>	1	\$ 36.00	+
83	REAR SILL TRIM STRIP - LH <i>Front RH</i>	1	\$ 165.00	+
84	REAR WHEEL HOUSING LINER - LH <i>Not Approved</i>	1	\$ 320.00	+
85	FRONT NO PLATE <i>Nec</i>	S/N	\$ 60.00	✓ 60
86	GLASS SEALANT <i>Nec</i>	1	\$ 100.00	✓ 100
87	ARCrylic SEALANT <i>2</i>	1	\$ 180.00	✓ 180
88	CRAVITY WAX <i>Nec</i>	1	\$ 140.00	✓ 140
89	STONE CHIP	1	\$ 180.00	✓ 180
90	SUNDRIES <i>Nec.</i>		\$ 500.00	? 81.28
TOTAL SPARE PARTS (FRONT + REAR)		:	\$ 76,136.00	
TOTAL LABOUR CHARGES		:	\$ 36,574.00	
GRAND TOTAL		:	\$ 112,710.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Adnan Lij
: 30/08/21

: Not Authorised, 22 Days. Rear: 14 Days
Front: 5 Days
Bumper, Door RW = 2 Days
Wheel Alignment = 1 Day
and Rims

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

22 Days.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

28 Days.
H.S.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT