

ASS. REG. BY:

REF: C77

OPTIMA WERKZ
SINGAPORE

 OPTIMA WERKZ PTE LTD
Co. Reg. No. 201212455W
www.ow.sg

f /OptimaWerkz

● /OptimaWerkz

 NOT Authorised
11 Sep @ 4300h
Penny After Pain
5 days

 Date: 30.08.2021
Vehicle No: SKS566D
Model: TOYOTA COROLLA ALTIS CLASSIC 1.6CVT
Chassis: MR053REH104523271-2014
Reg. Year: 2015

 Third Party Insurer: AIG
Third Party Veh No: GBL2976J
Date of Accident: 30.08.2021
Estimator: TING AN
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BOOTLID	1		Bt \$755.00
2	REAR BOOTLID "COROLLA" EMBLEM	1		me \$70.00
3	REAR BOOTLID "ALTIS" EMBLEM	1		me \$70.00
4	REAR BOOTLID LOGO EMBLEM	1		me \$80.00
5	REAR BOOTLID CHROME MOULDING	1		CM \$233.00
6	REAR BOOTLID WEATHERSTRIPE	1	92.30m	Dis/mt \$185.00
7	REAR BOOTLID INNER LOCK	1		Dis \$385.00
8	REAR BOOTLID INNER TRIM	1		Sm \$502.00
9	REAR BOOTLID LAMP LH	1		CM \$355.00
10	REAR BOOTLID LAMP RH	1		my CM \$355.00
11	REAR TAIL LAMP LH 380.10	1		my CM \$395.00
12	REAR TAIL LAMP RH 380.10	1		Dis/mt \$395.00
13	REAR BUMPER	1		Bu \$486.00
14	REAR BUMPER SIDE BRACKET LH	1		Dis \$110.00
15	REAR BUMPER SIDE BRACKET RH	1		Dis \$110.00
16	REAR BUMPER REFLECTOR LH	1		Sm \$60.00
17	REAR BUMPER REFLECTOR RH	1		CM \$60.00
18	REAR END PANEL	1		Bt \$590.00
19	REAR END PANEL UPPER COVER	1		my CM \$240.00
20	REAR SPARE TYRE UPPER BOARD	1		Sm \$267.00
21	REAR FENDER LH	1		REPAIR
22	REAR FENDER RH	1		REPAIR
	REAR BUMPER REINFORCEMENT	1		Bt \$250
SUB TOTAL				\$5,703.00
LESS 25%				-\$1,425.75
PARTS TOTAL				\$4,277.25

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER REVERSE SENSOR	1		Dis/mt \$300.00
2	REAR BUMPER CLIPS	1		me \$50.00
3	REAR END PANEL UPPER COVER CLIPS	1		me \$30.00
4	REAR END PANEL JOINT SEALANT	1		me \$60.00
S/N TOTAL				\$440.00

Head office

 6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

 8A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9010 | Fax: (+65) 6481 1003

Branch (Motor Insurance Claims)

 Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011


Date: 30.08.2021
Vehicle No: SKS566D
Model: TOYOTA COROLLA ALTIS CLASSIC 1.6CVT
Chassis: MR053REH104523271-2014
Reg. Year: 2015

Third Party Insurer: AIG
Third Party Veh No: GBL2976J
Date of Accident: 30.08.2021
Estimator: TING AN
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

\$1,200.00 - 600/

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOTLID, REAR BUMPER, REAR END PANEL, REAR FENDER LH, REAR FENDER RH & ETC.

\$1,200.00 600/

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

\$120.00 50/

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$100.00 60/

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$80.00 20/

LABOUR TOTAL \$2,700.00

TING AN TOTAL \$7,417.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

8 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 0010 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

