

NOT Authorised  
11 Sep 3  
Penny After Pain  
5 days

Date: 30.08.2021  
Vehicle No: SKS566D  
Model: TOYOTA COROLLA ALTIS CLASSIC 1.6CVT  
Chassis: MR053REH104523271-2014  
Reg.Year: 2015

Third Party Insurer: AIG  
Third Party Veh No: GBL2976J  
Date of Accident: 30.08.2021  
Estimator: TING AN  
Surveyor:

## ESTIMATE

| NO.         | DESCRIPTION                   | QTY | UNIT S\$ | AMOUNT S\$      |
|-------------|-------------------------------|-----|----------|-----------------|
| 1           | REAR BOOTLID                  | 1   |          | Rs \$755.00     |
| 2           | REAR BOOTLID "COROLLA" EMBLEM | 1   |          | Rs \$70.00      |
| 3           | REAR BOOTLID "ALTIS" EMBLEM   | 1   |          | Rs \$70.00      |
| 4           | REAR BOOTLID LOGO EMBLEM      | 1   |          | Rs \$80.00      |
| 5           | REAR BOOTLID CHROME MOULDING  | 1   |          | CM \$233.00     |
| 6           | REAR BOOTLID WEATHERSTRIPE    | 1   |          | \$185.00        |
| 7           | REAR BOOTLID INNER LOCK       | 1   |          | \$385.00        |
| 8           | REAR BOOTLID INNER TRIM       | 1   |          | Sn \$502.00     |
| 9           | REAR BOOTLID LAMP LH          | 1   |          | CM \$355.00     |
| 10          | REAR BOOTLID LAMP RH          | 1   |          | \$355.00        |
| 11          | REAR TAIL LAMP LH             | 1   |          | \$395.00        |
| 12          | REAR TAIL LAMP RH             | 1   |          | Red/Gn \$395.00 |
| 13          | REAR BUMPER                   | 1   |          | Bu \$486.00     |
| 14          | REAR BUMPER SIDE BRACKET LH   | 1   |          | Di \$110.00     |
| 15          | REAR BUMPER SIDE BRACKET RH   | 1   |          | Dr \$110.00     |
| 16          | REAR BUMPER REFLECTOR LH      | 1   |          | Rs \$60.00      |
| 17          | REAR BUMPER REFLECTOR RH      | 1   |          | CM \$60.00      |
| 18          | REAR END PANEL                | 1   |          | \$590.00        |
| 19          | REAR END PANEL UPPER COVER    | 1   |          | \$240.00        |
| 20          | REAR SPARE TYRE UPPER BOARD   | 1   |          | Sn \$267.00     |
| 21          | REAR FENDER LH                | 1   |          | REPAIR          |
| 22          | REAR FENDER RH                | 1   |          | REPAIR          |
|             | REAR BUMPER REINFORCEMENT     | 1   |          | Rs \$250        |
| SUB TOTAL   |                               |     |          | \$5,703.00      |
| LESS 25%    |                               |     |          | -\$1,425.75     |
| PARTS TOTAL |                               |     |          | \$4,277.25      |

| NO.       | SPECIAL NETT                     | QTY | UNIT S\$ | AMOUNT S\$      |
|-----------|----------------------------------|-----|----------|-----------------|
| 1         | REAR BUMPER REVERSE SENSOR       | 1   |          | Red/Gn \$300.00 |
| 2         | REAR BUMPER CLIPS                | 1   |          | Rs \$50.00      |
| 3         | REAR END PANEL UPPER COVER CLIPS | 1   |          | Rs \$30.00      |
| 4         | REAR END PANEL JOINT SEALANT     | 1   |          | \$60.00         |
| S/N TOTAL |                                  |     |          | \$440.00        |

### Head office

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

### Branch

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

### Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 30.08.2021  
Vehicle No: SKS566D  
Model: TOYOTA COROLLA ALTIS CLASSIC 1.6CVT  
Chassis: MR053REH104523271-2014  
Reg.Year: 2015

Third Party Insurer: AIG  
Third Party Veh No: GBL2976J  
Date of Accident: 30.08.2021  
Estimator: TING AN  
Surveyor:

**LABOUR CHARGES:**

|                                                                                                                                                          |            |         |
|----------------------------------------------------------------------------------------------------------------------------------------------------------|------------|---------|
| LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.                                                                   | \$1,200.00 | 500-600 |
| LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOTLID, REAR BUMPER, REAR END PANEL, REAR FENDER LH, REAR FENDER RH & ETC. | \$1,200.00 | 600     |
| LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.                                                                                     | \$120.00   | 50      |
| TO TUFF KOTE & UNDERSEAL MATERIALS.                                                                                                                      | \$100.00   | ?       |
| TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.                                                                                                               | \$80.00    | 20      |
| LABOUR TOTAL                                                                                                                                             | \$2,700.00 |         |

|         |       |            |
|---------|-------|------------|
| TING AN | TOTAL | \$7,417.25 |
|---------|-------|------------|

**Head office**

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

**Branch**

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

**Branch (Motor Insurance Claims)**

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

