

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009139/BUCN2**Date:** 04/10/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00107792101

Claimant Vehicle No : PC6105L **Insured Vehicle No :** SMJ8735D

Date of Loss: 03/08/2021 Nature of Claim: TP Claim No: SNM21D204300/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PC6105L**

Make & Model: ISUZU LT134P, 7.8 D (M) Engine No: 6HK1454510

Reg. Date: 15/11/2007 (Man. Year: 2007) Chassis No: JALLT134P77000139

Colour: Multi-colour Odometer: 439653 km

Engine Capacity: 7790 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80R22.5 Rear Tyre Size: 295/80R22.5

Front Left Side: Golden Crown 5 mm Rear Left Side: Triangle 5 mm

Front Right Side: Golden Crown 5 mm Rear Right Side: Triangle 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,635.00	3,740.00	12,895.00	77.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,050.00	2,130.00	2,920.00	57.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	21,685.00	5,870.00	15,815.00	72.93
Approved Total (Overridden) (\$\$)		4,700.00		
(\$\$)	21,685.00	4,700.00	16,985.00	78.33
+ GST 7.00/7.00% (\$\$)	1,517.95	329.00	1,188.95	78.33
Nett Amount (\$\$)	23,202.95	5,029.00	18,173.95	78.33

INSPECTION

Date of Assignment: 31/08/2021

Date Inspected: 01/09/2021 Inspected At: 160 SIN MING DR
#01-14 SIN MING AUTO CITY
SINGAPORE 575722
REPAIRER: TEAM AUTOPRO PTE LTD

Estimated Period of Repair: 6.0 days

Adjuster: Lim Teow Guan**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 04 Oct 2021)	
Parts:	N/A	ISUZU LT134P 7.8 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC6105L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
2	1		*RH DOOR COMPARTMENT 3	Repair	2,500.00 FS	*- FS
3	1		*RH DOOR COMPARTMENT 4	Broken	4,500.00 FS	*3,250.00 FS
4	2		*RH DOOR COMPARTMENT HINGE	Repair	640.00 FS	*- FS
5	2		*RH DOOR COMPARTMENT LOCK	Jammed	490.00 FS	*490.00 FS
6	2		*RH DOOR COMPARTMENT DAMPER	Not Damaged	360.00 FS	*- FS
7	1		*RH DOOR COMPARTMENT 5	Repair	6,800.00 FS	*- FS
8	2		*RH DOOR COMPARTMENT HINGE	Not Damaged	640.00 FS	*- FS
9	1		*RH DOOR COMPARTMENT LOCK	Not Damaged	245.00 FS	*- FS
10	1		*REAR WHEEL CHROME CAP	Not Damaged	380.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	16,635.00	3,740.00
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R RH DOOR COMPARTMENT 3	New	250.00	0.00
2	R&R RH DOOR COMPARTMENT 4	New	250.00	130.00
3	R&R RH DOOR COMPARTMENT 5	New	250.00	0.00
4	CHECK WIRING	New	100.00	0.00
5	PANEL BEATING	New	2,000.00	800.00
6	RUST PROOFING	New	200.00	0.00
7	SPRAY PAINTING	New	2,000.00	1,200.00
Gross Labour Cost (\$\$)			5,050.00	2,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >