

CARSMITH PTE LTD

Bartley Biz Centre, 13 Kaki Bukit Road 4, #01-20 Singapore 417807

Tel: +65 9091 0000 / Email @ claims@carsmith.biz

Car Number: **GBA5870T**

Date: **31/08/2021**

Model : **Suzuki Every**

Damaged Area: **(Rear Portion)**

Parts / Material :

1	Tailgate	\$	1,018.60
2	Tailgate inner trim board	\$	210.40
3	Tailgate inner trimboard clips (Set)	\$	25.00
4	Tailgate weatherstrip	\$	175.40
5	Tailgate inner lock	\$	125.80
7	Tailgate windscreen glass	\$	826.30
8	Tailgate logo "S"	\$	78.20
11	Taillamp assy RH	\$	386.70
12	Rear bumper	\$	580.40
14	Rear bumper bracket @ SGD 68.20	\$	136.40
15	Rear bumper clips (Set)	\$	35.00
20	Rear end panel	\$	486.70
22	Rear floor panel	\$	1,102.40
		\$	5,187.30
		Less Parts 15% :	\$ 778.09
		Total Parts :	\$ 4,409.20

Special Net Items :

Rear Tailgate Inner Glass inner Seal/Sponge Tap	\$	121.00
Rear Tailgate Glass Sealant	\$	80.00
Rear Tailgate Sticker (4 pax)	\$	30.00
Rear Tailgate Sticker (70km/h)	\$	30.00
Rear End Panel Sealant/Joint	\$	80.00
Reverse Sensor	\$	250.00
Rear Number Plate	\$	55.00
Total S/N Parts :		\$ 646.00

Labour :

To Remove, Repair & Renew Rear Affected Accident Areas (@ SGD 300.00 per day)	\$	1,000.00
To Putty, Spray Paint on Affected Accident Areas (@ SGD 300.00 per panel)	\$	1,000.00
To Check & Re-Connect all electrical wiring	\$	50.00
To Transfer Tailgate Attachment, Trims, Garnish to Facilitate Repairs	\$	120.00
To Remove & Install Rear Tailgate Glass to Facilitate Repairs	\$	150.00
To Conduct Water Seepage Test	\$	120.00
To Transfer Rear Compartment Trims, Garnish to Facilitate Repairs	\$	120.00
To Rust Proof Affected Areas	\$	200.00
Total Labour :		\$ 2,760.00

TOTAL PARTS :	\$	4,409.20
TOTAL SPECIAL NET ITEM :	\$	646.00
TOTAL LABOUR :	\$	2,760.00
TOTAL REPAIR COST :	\$	7,815.20