

CARSMITH PTE LTD

Bartley Biz Centre, 13 Kaki Bukit Road 4, #01-20 Singapore 417807

Tel: +65 9091 0000 / Email @ claims@carsmith.biz

Car Number: GBA5870T

Date: 31/08/2021

Model : Suzuki Every

Damaged Area: (Rear Portion)

Parts / Material :

- 1 Tailgate
- 2 Tailgate inner trim board
- 3 Tailgate inner trimboard clips (Set)
- 4 Tailgate weatherstrip
- 5 Tailgate inner lock
- 7 Tailgate windscreen glass
- 8 Tailgate logo "S"
- 11 Taillamp assy RH
- 12 Rear bumper
- 14 Rear bumper bracket @ SGD 68.20
- 15 Rear bumper clips (Set)
- 20 Rear end panel
- 22 Rear floor panel

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 1,018.60 *bt*
 \$ 210.40 *x*
 \$ 25.00 *x*
 \$ 175.40 *x*
 \$ 125.80 *bt*
 \$ 826.30 *bro*
 \$ 78.20 *re*
 \$ 386.70 *ca*
 \$ 580.40 *de*
 \$ 136.40 *x*
 \$ 35.00 *re*
 \$ 486.70 *ry*
 \$ 1,102.40 *x*

Less Parts 15% : \$ 778.09
 Total Parts : \$ 4,409.20

Special Net Items :

- Rear Tailgate Inner Glass inner Seal/Sponge Tap
 Rear Tailgate Glass Sealant
 Rear Tailgate Sticker (4 pax)
 Rear Tailgate Sticker (70km/h)
 Rear End Panel Sealant/Joint
 Reverse Sensor
 Rear Number Plate

\$ 121.00 *re*
 \$ 80.00 *40*
 \$ 30.00 *re*
 \$ 30.00 *re*
 \$ 80.00 *x*
 \$ 250.00 *200*
 \$ 55.00 *x*

Total S/N Parts : \$ 646.00

Labour :

- To Remove, Repair & Renew Rear Affected Accident Areas (@ SGD 300.00 per day)
 To Putty, Spray Paint on Affected Accident Areas (@ SGD 300.00 per panel)
 To Check & Re-Connect all electrical wiring
 To Transfer Tailgate Attachment, Trims, Garnish to Facilitate Repairs
 To Remove & Install Rear Tailgate Glass to Facilitate Repairs
 To Conduct Water Seepage Test
 To Transfer Rear Compartment Trims, Garnish to Facilitate Repairs
 To Rust Proof Affected Areas

\$ 1,000.00 *600*
 \$ 1,000.00 *600*
 \$ 50.00 *30*
 \$ 120.00 *60*
 \$ 150.00 *120*
 \$ 120.00 *30*
 \$ 120.00 *60*
 \$ 200.00 *30*

Total Labour : \$ 2,760.00

TOTAL PARTS : \$ 4,409.20
 TOTAL SPECIAL NET ITEM : \$ 646.00
 TOTAL LABOUR : \$ 2,760.00
 TOTAL REPAIR COST : \$ 7,815.20

2589.10
 421
 1530
 4540.10

Tanpin 97425769
 - WP 31/8/21 430pm
 1/5 Resurvey after repair
 05 days

3632.08
 1/5 \$2500
 05 days. Repair limit \$2500.