

REG. NO. (V)

Thuan

China

# ASSIGNMENT

From

Date

Estimated Cost:

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$56447.93

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHA9498M

Yr Regn:

9/10, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Ioniq

c.c. 1580

Colour

Yellow

A/C: Insured / Std / NI / NA

Sp. Reading

15346

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

hmhc85/cvlu178518

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SIRIM / STD AIRIM or

Tyre Size:

F:

195/65R15

R:

195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

26/8/21

D.O.I.

27/8/21 1645

Survey held at

Comfort

Des. of Damages: (Fr) (Rear) / OIS / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

rebate: 28496

NV: 29451.93

\*Note: Some parts prices need verification!

31/8/2021

Date/Time File Pass to?

☐

; Prelim. Report

1)

☐

; Final Report

Date/Time File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Finishes

Others

Total

Add Fee:

☐

; Site Insp (\$

☐

; Interview (\$

☐

; Tech. Invs (\$

☐

; MVA/and (\$

Report Fee:

Letter Sign / B.J.:

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	839G

### Vehicle Details

Vehicle No.:	SHA9498M
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Aug 2021
Vehicle Make:	HYUNDAI
Vehicle Model:	AE IONIQ HEV FL 1.6 DCT
Primary Colour:	Yellow
Manufacturing Year:	2019
Engine No.:	G4LEKU362757
Chassis No.:	KMHC851CVLU178518
Maximum Power Output:	103.6 kW (138 bhp)
Open Market Value:	\$25,792.00
Original Registration Date:	09 Oct 2019
First Registration Date:	09 Oct 2019
Transfer Count:	0
Actual ARF Paid:	\$13,109.00

### Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Oct 2027
PARF Rebate Amount:	\$9,831.00

### Intended COE Rebate Details

COE Expiry Date:	08 Oct 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$24,460.00
COE Rebate Amount:	\$18,665.00
<b>Total Rebate Amount:</b>	<b>\$28,496.00</b>

### Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 30 Aug 2021

OK

72  
B-6-1.5  
73.5 mths

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	26/08/2021 18:18 (SGT)
Date of Accident	26/08/2021 14:50 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	TOWARDS TUAS
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA9498M
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	CITYCAB PTE LTD
Company Reg No	1XXXXX839G
Email Address	fleetsafety@cdgtaxi.com.sg
Mobile Phone No	(Phone) +65-93626686
Alternative Phone No	(Office) +65-65508768

#### VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	Ae ioniq
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1580

#### INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	ThirdPartyFireTheft
Fleet Policy	Yes
Policy Number	VFX/P2419140
Cover Note Number	-

#### DRIVER

Name of Driver	TAN SHU KUN (CHEN SHUKUN)
NRIC No	SXXXX301A

## COMFORT TRANSPORTATION PTE LTD

## REPAIR ESTIMATE

Date: 27.08.2021

Vehicle No. : SHA9498M

Make : HYUNDAI

Model : IONIQ(G3)

Veh Reg Date: 09/10/2019

Insurance: CHINA TAIPING

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount	
	Bonnet			\$2,253.80	✓ DIF
	Bonnet Rubber LH			\$118.70	✓ SVC
	Bonnet Rubber RH			\$118.70	✓ SVC
	Bonnet Hinge LH RH		\$118.70	\$237.40	✓ BT
	Bonnet Moulding			\$41.40	✓ DIF
	Bonnet Lock			\$127.30	✓ Jam
	Bonnet Absorber			\$35.70	?
	Bonnet Insulator			\$230.10	✓ nec
	Bonnet Seal			\$38.30	✓ nec
	Bonnet Insulator Clips			\$15.00	?
	Radiator Grille			\$1,409.10	✓ ?
	Radiator Grille Up			\$48.30	✓ cut
	Front Number Plate Garnish			\$188.00	✓ cut
	Radiator H Emblem			\$31.30	✓ cut
	Unit Assy-SMART CRU (Radar Sensor)		2,503.05	\$2,910.90	✓
	Cover Assy -S.C.C.Unit			\$767.30	?
	Antenna Assy SMARTKEY LH RH		\$80.20	\$160.40	?
	Wiring Harness BWS Ext			\$988.90	?
	Front Bumper Cover			\$430.90	✓ cut
	Front bumper top cover			\$476.30	✓ cut
	Front Bumper Sponge			\$186.90	✓ cut
	Front Bumper Sponge/Absorber			\$96.90	?
	Front Bumper Reinforcement		609.96	\$1,075.10	?
	Front Bumper Reinforcement ABSORBER LH RH			\$186.50	?
	Front Bumper Moulding Centre Upper			\$368.50	✓ cut
	Front Bumper Grille LH			\$186.90	✓ cut
	Front Bumper Towing Cover			\$29.00	✓ cut
	Front Bumper Centre Moulding			\$188.00	✓ cut
	Front Bumper Moulding			\$187.20	✓ cut
	Front Bumper Lower Stiffner			\$285.10	?
	Front Bumper Lip			\$35.10	✓ SVC
	Front Bumper Bracket Top LH RH			\$70.00	✓ nec
	Front Bumper Bracket LH RH			\$56.00	✓ nec
	Front Bumper Clips 10 pcs			\$22.00	✓ nec
	Front Bumper Centre Grille			\$318.80	✓ cut
	front bumper lower grille moulding			\$127.60	✓ SVC
	Front bumper air duct LH RH			\$153.80	?
	Headlamp Support Panel Assy			\$949.30	?
	Headlamp LH RH		\$1,993.65	\$3,987.30	1993.65 (LH)
	Day Light ,LH			\$642.50	✓ SVC
	Day Light Wire, LH			\$585.50	✓ SVC
	BUZZER ASSY - PIEZO (LH)			\$388.00	?
	Radiator Inverter			\$884.80	?
	Radiator			\$710.50	?
	COOLANT			\$45.00	?

Qty	Parts Description / Labour	Type	Unit Price	Amount
	Radiator Fan			\$375.10 ?
	Radiator Hose Upper			\$166.20 ?
	Radiator Hose Lower			\$156.20 ?
	Radiator Hose Water			\$123.50 ?
	Radiator Pipe Water			\$176.30 ?
	Radiator Tank Reservoir			\$196.50 ?
	Radiator Hose & Tube Assy			\$245.70 ?
	Radiator Air Guard (LH/RH)		\$38.20	\$76.40 ?
	Radiator Air Guard, Upr(LH/RH)		\$63.75	\$127.50 ?
	Horn Unit			\$72.80 ?
	Horn Wire			\$386.70 ?
	Front Fender LH			\$588.80 ✓ DIF
	Front Fender Shield LH			\$164.70 ?
	Front Fender Retainer			\$82.80 ✓ ncc
	Emblem Blue -Drive			\$26.60 ✓ ncc
	Aircon Expansion Valve			\$313.60 ?
	Aircon Condenser			\$663.60 ?
	Aircon Suction & Liquid Hose			\$679.60 ?
	Aircon Discharge Hose			\$148.50 ?
	Aircon Blower Motor			\$567.50 ?
	Battery Tray			\$234.80 ?
	Front Windscreen Pillar Outer RH			\$3,764.90 X r
	REAR BUMPER COVER			\$459.40 ✓ cut
	REAR BUMPER CLIPS			\$22.00 ✓ ncc
	REAR BUMPER CENTRE MOULDING ASSY			\$451.25 ✓ cut
	REAR BUMPER REINFORCEMENT			\$394.80 ?
	REAR BUMPER REINFORCEMENT BRACKET LH RH		\$138.10	\$276.20 ?
	REAR BUMPER LOWER CTR MOULDING			\$155.00 X r
	REAR BUMPER TOWING COVER			\$98.80 X SVC
	REAR BUMPER FOG LAMP			\$201.50 X SVC
	REAR BUMPER UNDER COVER			\$225.00 X SVC
	LICENCE LAMP			\$85.30 ✓ DIS
	BOOTLID			\$2,480.40 X r
	BOOTLID HINGE LH RH		\$31.30	\$62.60 ✓ sum
	BOOTLID KEY LOCK			\$141.00 X SVC
	BOOTLID HYUNDAI PLATE			\$24.30 ✓ ncc
	EMBLEM HYBRID			\$24.30 ✓ ncc
	EMBLEM – IONIQ			\$31.30 ✓ ncc
	REAR PANEL			\$532.00 ?
	REAR PANEL GARNISH			\$346.80 ?
	ANTENNA ASSY SMARTKEY			\$40.50 ?
	EXHAUST SILENCER			\$943.50 ?
	EXHAUST PIPE HANGER			\$29.20 ?
	SUB TOTAL			\$38,757.55
	LESS 20%			\$7,751.51
	DISCOUNTED TOTAL			\$31,006.04
1	FRT NUMBER PLATE WITH TRIM COVER			\$55.00 Nett ✓ slv
1	BOOTLID COMFORT TEL NO STICKER			\$35.00 Nett ✓ ncc

Qty	Parts Description / Labour	Type	Unit Price	Amount	
1	BOOTLID COMFORT LOGO STICKER			\$30.00	Nett ✓ nec
1	BOOTLID COMFORT APP STICKER			\$30.00	Nett ✓ nec
1	REAR NUMBER PLATE WITH TRIM COVER			\$55.00	Nett ✓ scr
1	REAR BUMPER RUBBER MAT			\$50.00	Nett ✓ <del>scr</del> nec
1	REAR BUMPER REVERSE SENSOR			\$180.00	Nett ✓ cut
				<b>\$435.00</b>	nett
	<b>Labour Charge</b>				
	PANEL BEATING			\$2,500.00	1750
	SPRAY PAINTING CHARGE			\$2,000.00	1250
	REMOVE / REFILL AIRCON & REFILL GAS			\$150.00	30
	REMOVE/ REFILL RADIATOR			\$90.00	30
	REMOVE/ REFILL EXHAUST PIPE			\$150.00	30
	TOWING CHARGE			\$60.00	✓
	TUFF KOTE			\$120.00	30
	CHECK WIRING			\$120.00	30
	<b>TOTAL LABOUR</b>			<b>\$5,190.00</b>	
	<b>Emblem-Blue Drive (LH/RH)</b>				
	<b>ESTIMATE TOTAL</b>			<b>\$36,631.04</b>	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

Thuan LKH

82235769 thuan@lkhauto.com

P/P before paint ~~photo~~ photos

27/8/21 1645

6 days wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



USER ID : CTNNEX03  
PAGE : 1

Veh. Age : 022

[illegible]