



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI21009144/Avf3e2	
			Date: 22/11/2021	
			Code: UOI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBK 9783H	Veh. Inspected	SKS 7718L
	Policy No.		Coverage (\$)	0.00
	Claim No.	M12D16482109	Excess (\$)	0.00
	Assign From	JOSEPHINE WONG	Assign Date	31/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ B180	c.c	1699
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	WDD2452322J575726	Colour	SILVER
	Odometer	162455 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/40 R18	TOURADOR	6 mm
	L/H Front Tyre	225/40 R18	TOURADOR	6 mm
	R/H Rear Tyre	225/40 R18	TOURADOR	6 mm
	L/H Rear Tyre	225/40 R18	TOURADOR	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/08/2021	Inspection Date	01/09/2021
	Survey held at	BEST SOLUTION AUTOCARE PTE LTD 53 UBI AVE 1 #03-01 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	