

BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D

☎ 6744 0777

☎ 6744 2377

Estimate Quotation

Quotation No	Aug 002/2021
Date	28/8/21
Vehicle No	SKS7718L
Make / Model	Mercedes B180

To: United Overseas Insurance Ltd

Address: 3 Anson Rd, Singapore 079909

W002452322JS75726

Qty	DESCRIPTION	UNIT	Amount
	Items		
1 pc	front bumper <i>Dehd</i>		\$ 1215 1,450.00 ✓
1 set	front bumper clip <i>re</i>		\$ 40.00 ✓
1 pc	front bumper chrome trim <i>cut</i>		\$ 98 250.00 ✓
1 pc	front bonnet <i>Dehd</i>	5583	\$ 1,850.00 ✓
1 pc	n/s front head lamp <i>cut</i>	5024.70	\$ 1250 1,485.00 ✓
1 pc	n/s front fender <i>Dehd</i>		\$ 840.00 ✓
1 pc	n/s fog lamp chrome garnish <i>not included</i>	S.N: 500	\$ 195.00 ✓
1 pc	n/s sport rim <i>cut</i>		\$ 500 (sw) 950.00 ✓
1 set	front bumper side retainer <i>re</i>		\$ 95.00 ✓
1 pc	wheel bearing <i>3 new</i>		\$ 480.00 ✓
1 pc	front absorber		\$ 685.00 ✓
	Labour Charge		
1	to dismantle damaged parts, panel beat, repair		\$ 900.00 600 ✓
2	to putty and spray painting on affected area		\$ 900.00 800 ✓
3	anti rust		\$ 1560 80.00 50 ✓
4	check wheel alignment		\$ 150.00 80 ✓
5	electrical wiring check		\$ 80.00 30 ✓
6	undercarriage		\$ 120.00 ✓
Subtotal:			\$ 10,550.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BEST SOLUTION AUTOCARE PTE LTD

Authorised Signature

Adrian L
4/8 01/09/21

05 Days

total: 7084.70

L/S: 5.6K ✓