

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

India International Insurance Pte Ltd

64 , Cecil Street # 04 - 05
 IOB Building
 Singapore 049711
 Tel : 6347 - 6100
 Fax : 6224 - 4174

Quotation

DATE : 03.09.2021
 VEH NO : SDJ9989M
 MODEL : Toyota Harrier
 D O A : 30.08.2021
 YR REF : SLU2527G

Jasper.

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SDJ9989M (TOYOTA HARRIER)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Front Bumper <i>Dehd</i>	1	1,450.40 ✓
2	Front Bumper Side Holder - LH & RH <i>over</i>	2	196.20 ✓
3	Front Bumper Lower Grille <i>crackd</i>	1	365.00 ✓
4	Front Bumper Lower Garnish <i>re m</i>	1	378.10 X.
5	Front Bumper Undercover <i>Dehd</i>	1	301.70 ✓
6	Front Bumper Centre Sponge <i>crackd</i>	1	172.00 ✓
7	Front Bumper Reinforcement <i>re m</i>	1	490.60 X.
8	Front Bumper Center Beam <i>Bent</i>	1	236.80 ✓
9	Front Grille <i>crackd</i>	1	536.10 ✓
10	Head Lamp - LH & RH <i>LH cracked</i>	2	7,060.20 3530.10
11	Head Lamp Lower Sponge - LH & RH <i>LH cracked</i>	2	224.40 112.20
12	Front Brace Panel <i>Bent</i>	1	226.10 ✓
13	Front Support Panel <i>Repair</i>	1	798.50 X.
14	Front Support Panel Top Cover <i>re m</i>	1	280.40 X.
15	Front Fender - LH <i>Buckled</i>	1	1,090.50 ✓
16	Bonnet <i>Dented</i>	1	1,880.40 ✓
17	Bonnet Lock <i>re m</i>	1	145.60 X
18	Bonnet Outer Moulding <i>Missing</i>	1	295.40 ✓
19	Air Con Condenser <i>Bent</i>	1	1,447.80 ✓
20	Air Con Condenser Side Guide <i>LH Dehd</i>	2	70.00 35
21	Radiator <i>re m</i>	1	1,860.30 X.
			19,506.50
Less 25%			(4,876.63)
			\$ 14,629.88

11875.70
8906.77

S/NET ITEMS

RE : ESTIMATE FOR ACCIDENT REPAIR SDJ9989M (TOYOTA HARRIER)

1	Front Number Plate	<i>3 new</i>	1	30.00	<i>x</i>
2	Front Number Plate Holder		1	30.00	<i>x</i>
3	Front Bumper Clips	<i>new</i>	1 set	30.00	<i>✓</i>
4	Front Bumper Undercover Clips	<i>new</i>	1 set	25.00	<i>✓</i>
5	Front Grille Clips	<i>new</i>	1 set	20.00	<i>✓</i>
6	Front Support Panel Top Cover Clips	<i>new</i>	1 set	30.00 20.	
7	Bonnet Outer Moulding Clips	<i>new</i>	1 set	20.00	<i>✓</i>
8	Air Con Condenser Side Guide Clips	<i>new</i>	1 set	20.00 10.	
				125	
				205.00	

Total Parts **\$ 14,834.88**

LABOUR CHARGE

1	To knocking & pull out front portion & renew above parts	\$	1,200.00 800.
2	To putty & spray up paint works	\$	1,200.00 950
3	To check wiring	\$	50.00 30
4	To remove condenser & top up aircon gas	\$	120.00 60.
5	To remove radiator & to up coolant	\$	120.00 x
		1840	
Total Labour		\$	2,690.00

Grand Total **\$ 17,524.88**

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

total: 10871.77
4/5 8.71K
6 DAYS