

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLH 320/H
 at Workshop m/s: 74444444
 of: _____

Insured: FSR6022D

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: \$ 90k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: Rep 146

Date / Time Action / Instruction
have video

Veh No: SLH 320/H Yr Regn: 28/10/16

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A) Aeros premium

Make: Toyota Estima C.C. 2362

Colour: white A/C: Insured / Std / NI / NA

Sp.Reading: 78748 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ACR 507133467

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50 R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 2 mm R/Bal. 2 mm

L/Bal. 2 mm L/Bal. 2 mm

D.O.A. 28/8/21 D.O.I. 22/9/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) ___ \$ + RS ___ \$

) Photos

) Others

)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

22/9/24 2/381400 confirmed with million

III Insured's Veh No : FBR6022D
Date of Accident : 28 August 2021



陳林摩呀私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Miss Loke Pui Wai Cynthia

Date : 01 September 2021

Estimate To Repair SLH3201H - Toyota ESTIMA AERAS PREMIUM 2.4 A
Chassis No : ACR507133467

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	Rear bumper 211	\$ 1,355.80
02	6 ps	Rear bumper clips @ \$4.50 111	\$ 27.00
03	1 pc	Rear bumper reflector - o/s 17	\$ 328.00
04	1 pc	o/s rear fender 12	\$ 855.00
05	1 pc	o/s rear fender inner cooling 17	\$ 95.00
06	6 ps	o/s rear fender inner cooling clips @ \$4.30 17	\$ 25.80
07	1 pc	o/s tyre rim 211	\$ 1,050.00
Less 25 %			\$ 3,736.60
			\$ 934.15
			\$ 2,802.45
<u>SPECIAL NETT ITEMS</u>			
08	1 pc	o/s rear fender 1/4 glass primer 17	\$ 40.00
09	1 pc	o/s rear fender 1/4 glass inner seal 17	\$ 120.00
10	1 pc	o/s rear fender 1/4 glass sealant 17	\$ 80.00
			\$ 240.00
<u>LABOUR & MISC. CHARGES</u>			
01		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 700.00
02		To check electrical lighting concerned.	\$ 80.00
03		To reinstall of rear bumper parking sensor.	\$ 80.00
04		To transfer of tyre, rim and on wheel balancing.	\$ 50.00
05		To upholstery and make good repair to cushion seat and seat frame and reclining mechanism.	\$ 200.00
06		Putty and spray painting of the affected portion.	\$ 800.00
			\$ 1,910.00
Total			\$ 4,952.45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

acc! L44-Marcus

22/09/2021 004/10/11

1,445.68