

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHD4980D

Yr Regn:

25/10, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Ionig

c.c 1580

Colour

blue

A/C: Insured / Std / NI / NA

Sp. Reading

248036

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

hmtlc85/culu187445

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or westlake

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

25/8/21

D.O.I.

26/8/21 1545

Survey held at

Comfort

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Roof/top or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

NO GIA given

Date/Time File Pass to?

☐

: Prelim. Report

1)

☐

: Final Report

Date/Time File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS. \$

Fuel

Other

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Wash and

Request Form:

Link: 2011/11/11

Veh Reg : 25-10-19
PIP

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHD4980D

Date: 25/08/2021

Make : HYUNDAI

Insurance: NTUC

Model : IONIQ(G3)

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$459.40 Xr
10	REAR BUMPER CLIPS			\$22.00 /nec
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25 /cut
1	REAR BUMPER REINFORCEMENT			\$394.80 ?
1	REAR BUMPER REINFORCEMENT BRACKET LH RH		\$138.10	\$276.20 ?
1	REAR BUMPER LOWER CTR MOULDING			\$155.00 /DIS
1	REAR BUMPER REFLECTOR LAMP LH			\$41.45 X Svc
1	REAR BUMPER TOWING COVER			\$98.80 /cut
1	REAR BUMPER FOG LAMP			\$201.50 X Svc
1	BOOTLID			\$2,480.40 /DIF
1	BOOTLID HYUNDAI PLATE			\$24.30 /nec
1	EMBLEM HYBRID			\$24.30 /nec
1	EMBLEM - IONIQ			\$31.30 /nec
1	ANTENNA ASSY SMARTKEY			\$40.50 ?
1	LICENCE LAMP			\$85.30 X Svc
	SUB TOTAL			\$4,786.50
	LESS 20%			\$957.30
	DISCOUNTED TOTAL			\$3,829.20
	REAR NUMBER PLATE + TRIM COVER	-10%		\$55.00 /ora
	REAR BUMPER RUBBER MAT			\$50.00 /nec
1	BOOTLID COMFORT TEL NO STICKER	-10%		\$35.00 /nec
1	BOOTLID COMFORT LOGO STICKER	-10%		\$30.00 /nec
1	BOOTLID COMFORT APP STICKER	-10%		\$30.00 /nec
1	REAR BUMPER REVERSE SENSOR	-10%		\$180.00 /cut
				\$380.00
	Labour Charge			
	PANEL BEATING			\$800.00 5205
	SPRAY PAINTING CHARGE			\$600.00 500
	WIRING CHARGE			\$50.00 70
	REMOVE/REFIX REVERSE SENSOR			\$80.00 30
	TOTAL LABOUR			\$1,530.00
	ESTIMATE TOTAL			\$5,739.20

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

INSURER ENQUIRY

Find

insurer

Vehicle reg. no.

GBL1039X

Date of Accident

25/08/2021 

Reset

% RESULT & RECEIPT

TP Insurer Enquiry

Insurance NTUC Income Insurance Co-op...

Period of Insurance 15/03/2021 - 14/03/2022

Requested By Janet Lim Siang Gek (COMFOR...

Requested Date 25/08/2021 12:55

Payment details

Request Amount: **S\$1.87**GST Amount: **S\$0.13**Total Amount Due (GST Inclusive): **S\$2**

General Insurance Association

Records Management Centre

GST Registration No: **M400017735**Thuan Lhk 

82235769 thuan@lhkauto.com

1545 25/8/21

P/p ~~at~~ before paint photo

3 days w/p

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are based on "market" basis
- Third party survey is not on "no-fault" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: