

REPAIR ESTIMATE*

VEHICLE NO SHC1248K

MAKE 27.02.2019

DATE 26/08/21

MODEL : HYUNDAI IONIQ G2

CHIANG /NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER			\$430.90
1	RADIATOR GRILLE			\$1,409.10
1	FRONT CENTRE MOULDING			\$368.50
1	HEAD LAMP LH			1,193.65 1993.65
10	BUMPER CLIP			\$22.00
1	FRONT NUMBER PLATE MOUNTING			\$188.00
				\$4,412.15
	20.00% DISCOUNTED TOTAL			\$882.43
				\$3,529.72
1	NUMBER PLATE W/HOLDER			\$55.00
				\$55.00
	Labour Charge			
	Panel Beating			\$550.00
	Spray Paint			\$300.00
	Check lighting			\$60.00
	TOTAL LABOUR			\$910.00
	ESTIMATE TOTAL			\$4,494.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuan Lkh
82235769 thuan@lkhauto.com
26/8/21 1645
2 days wp
L/S after repair photos

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date: