

REC BY: Thuan

Ntuc

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC1248K

Yr Rogn: 77/2, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) Prime Mover /

Truck / Trailer or

Make: Hyundai

c.c 1580

Colour: blue

A/C: Insured / Std / NI / NA

Sp. Reading: 213/64

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KmH0851CV1u/40861

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SIRIM / STD A/Rim or

Tyre Size: F: 195/65R15

R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

westlake

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 26/8/21

D.O.I. 26/8/21

1645

Survey held at

Comfort

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

NO GIA given

Date/Time File Pass to?

☐

: Prelim. Report

1)

☐

: Final Report

Date/Time File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Finals

Others

Total

Add Fee: _____

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Insp (\$ _____)

☐

: Wash and _____

Insured's Signature:

Insured's Stamp/Signature:

REPAIR ESTIMATE*

VEHICLE NO SHC1248K

DATE 26/08/21

MAKE 27.02.2019

MODEL : HYUNDAI IONIQ G2

CHIANG /NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER			\$430.90
1	RADIATOR GRILLE			\$1,409.10
1	FRONT CENTRE MOULDING			\$368.50
1	HEAD LAMP LH		1,198.80	\$1,993.65
10	BUMPER CLIP			\$22.00
1	FRONT NUMBER PLATE MOUNTING			\$188.00
				\$4,412.15
		20.00%		\$882.43
	DISCOUNTED TOTAL			\$3,529.72
1	NUMBER PLATE W/HOLDER			\$55.00
				\$55.00
	Labour Charge			
	Panel Beating			\$550.00
	Spray Paint			\$300.00
	Check lighting			\$60.00
	TOTAL LABOUR			\$910.00
	ESTIMATE TOTAL			\$4,494.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuan Lkh
82235769 theuan@lkhauto.com
26/8/21 1645
2 days w/p
L/C after repair photos

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 26.08.2021 14:27

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD

Sales Order:


JC NO.: 305484305

STOMER	REGN NO.: SHC1248K	MILEAGE
VMS	MAKE: HYUNDAI	FUEL
STOMER NO. 7010045	MODEL	E.....1/2.....F
DRESS 383 SIN MING DRIVE	YR OF MANU. 27.02.2019	DATE/TIME IN 26.08.2021 10:50
Singapore SINGAPORE 575717	CHASSIS CODE	TARGET DATE
65508755 (R) (P)	KMHC851CVKU140861	COMPLETION DATE/TIME:
COUNT CARD NO.		

JOB DESCRIPTION

Accident Date: 26.08.2021
NATURE: 3P 26.08.2021

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHC1248K CHIANG

Vehicle No.: SHC1248K

Signature/Date

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard