					COMFORTDELGRO				
Our Job Ref No : 305484188					ENGIN	VEERING -			
Date : 28/08/21			•		ComfortDelGro Engineering Pte Ltd				
FINA	LIZATI	ON FORM			59 Loyang Drive Singapore 508969 Fax: 6546 8156				
То	:	L	KK		Fax:				
Attn	:	TH	HEVAN						
Vehic	le Reg	No. : SHA2	7 <mark>8</mark> 4H	Da	te of Accident :_	25.08.21			
The s	urvey	and estimates of th	ne repairs of the ab	ove-mentione	ed vehicle are as	follows:-			
1.	The r	epair job shall bill t	0:	NTUC		SJV2714B			
2.	The finalized amount shall be:								
	(a)	Spare Parts after	List discount						
	(b)	Labour Charges							
		Total for Part-By							
	(c.)	Lumpsum Repair Total for Lumpsui		\$2,850.00					
		Final Lumpsum		Less: 20%		\$2,850.00			
3.	Estimated normal period for repairs:3working days.								
4.		hall treat the aboven 7 working days	ve amount as Corr	ect and Con	firmed if there is	s no reply from you			
5. Thank you for your assistance.				We confirm the estimates and finalized amount					
	imes								
	Signa		Ov. (	- S	TUENAN				
Name : LIM T S  Tel : 62148398				-	ame :	THEVAN			
			8	- D	ate :	9   2			
	Fax	: 65468156	6	-					
For O	fficial	Use Only							
		Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks			
1. Re	Rental Rate P/Day			YES					
2. Lo	Loss of Income Paid			N					
3. Survey Fees		ees							
LTA Search Fee     Medical Fees (on behalf of		rch Fee	\$7.49 /\$2.00						
5. Me	ver, if	ees (on behalf of applicable)							
	errun								
Rema	ırks:								

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

Effective Date: 1 Nov 2020

LKK-

DATE:

25-Aug-21

MODEL:

Hyundai i40

VEHICLE NO. SHA2784H

INSURANCE: NTUC CL S

MVA: LIM TS

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
					/
	Front Bumper	1		\$1,052.20	CU
	Front Bumper Clips	10	\$2.20	\$22.00	nce
	Front Bumper Side Bracket RH	1		\$22.40	nu
	Front Fender RH	1		\$663.00 X	1
	Front Fender Shield RH	1	au la	\$174.90 X	
	Front Fender Retainer RH	1	54.60	\$217.20	-
	HeadLamp RH	1	VRAG	\$1,800.00	200
	Front Wheel Cap RH	1		\$217.20	50
	SUB TOTAL			\$4,168.90	
	LESS 20%			\$833.78	
	DISCOUNTED TOTAL			\$3,335.12	
	Diocom 25 ionia				1
	Front Fender Adv.Sticker RH	1		\$100.00	1
	TOTAL SPARE PARTS			\$3,435.12	
	Labour Charge				
	Panel Beating			\$800.00	4
	Spray Painting Charge			\$600.00	50
	Check Lightings	ri		\$40.00	3
	Tuff Kote			\$60.00	3
	TOTAL LABOUR			\$1,500.00	1
	ESTIMATE TOTAL			\$3,535.12	1

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Theyan Lth & 82235769 thwan@Lthauto. wm 1530 285/8/21 L/S after repair photos 3days wip

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: