



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2348Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR DOOR PANEL RH	TO REPAIR SEE LABOUR	1,789.90	-
1	FRONT DOOR PROTECTOR RH	SCRATCHED	110.10	110.10
1	REAR DOOR PROTECTOR RH	SCRATCHED	125.30	125.30
	LESS 20% DISCOUNT		-405.06	-47.08
			1,620.24	188.32
NETT ITEMS				
1	FRONT DOOR COMFORT LOGO STICKER (N)	NECESSARY	75.00	75.00
1	REAR DOOR COMFORT APP STICKER (N)	NECESSARY	80.00	80.00
	LESS 10% DISCOUNT		-15.50	-15.50
			139.50	139.50
LABOUR				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR DOOR PANEL RH.		600.00	350.00
	SPRAY PAINTING CHARGE.		900.00	500.00
	REMOVE/REFIX DOOR PARTS.		90.00	30.00
	CHECK WIRING.		60.00	20.00
			1,650.00	900.00
GRAND TOTAL			3,409.74	1,227.82
RECOMMENDED COST OF REPAIRS (CONFIRMED)				1,227.82

Report Ref No. NS/INC21009157/Vvcn2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT (RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.