

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : SLN9346C

Accident Date : 26/8/2021

Location : BLK 503 WEST COAST DRIVE AYER RAJAH HAWKER CENTRE CARPARK

Model: HYUNDAI VELOSTER

(23/5/2017)

3P: GU9872Y (III)

TP III
xiao Tony.

KMHTC61CMJ4319663

S/No s.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front bumper <i>for</i>	763.50	✓	
2	10 pcs	Front bumper clips <i>re</i>		40.00	30
3	1 pc	Front bumper o/s fog lamp <i>re</i>	566.40	✓	
4	1 pc	Front bumper o/s retainer <i>re</i>	84.40	✓	
5	1 pc	Front o/s head lamp <i>re</i>	2455.70	✓	
6	1 pc	Front o/s fender <i>Regr</i>	677.50	+	
7	1 pc	Front o/s fender inner trim <i>re</i>	154.60	+	
8	1 pc	Front o/s rim <i>re</i>	1172.90	+	
9	1 pc	Front o/s washer tank <i>re</i>	96.60	X	
		Sub-Total:	4,971.60	40.00	0.00
			20%	0%	0%
		After Less %:	3,977.28	40.00	0.00

3303.60

SA: 30

2642.88

Labour		
1	To dismantle, straighten & welding.	800.00
2	To spray painting.	600.00
3	To check wheel alignment	150.00
4	To check for fault code and program front o/s head lamp	300.00
5	To check wiring.	50.00
6	To re-seal anti-rust.	30.00
	Sub-Total:	1,930.00
	Total:	5,947.28
	AFTER LESS 20%	4,757.82

730.

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Date:

