Our Jo	ob Ref N	0 : 30	5484953	COMFORTDELGRO				
Date		; 0	2/09/21	ComfortDelGro Engineering Pta Lld 59 Loyang Drive Singapore 808989				
FINAL	LIZATIO	NFORM						
To LKK				Fax :				
Attn THEVAN			THEVAN	-				
Vehic	le Reg N	Io. SHA10	29L	29/08/2021				
The s	survey at	nd estimates of the	repairs of the above-mention	oned vehicle are	as follows:-			
Z	The re	pair job shall bill to	): 	AIG		SGD6181S		
2.	The fir	alized amount sha	all be:					
	(a) Spare Parts after List discount							
	(b) Labour Charges							
	Total for Part-By-Part Repair Cost							
	(c.)	(c.) Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: Final Lumpsum Repair cost				\$1,150.00		
3. 4.	Estimated normal period for repairs: 2 working days.  We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days							
5.		you for your assi	stance.	We confirm the estimates and finalized amount				
	Name : CHIANG			_	nature :	Thevan 7/9/21		
				_ Nar				
			4	_ Dat	ie :			
	Fax	: 6546815	3	_				
For	Official	Use Only						
	Item		Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks		
1. F	. Rental Rate P/Day			YES				
2. L	2. Loss of Income Paid			N				
3. Survey Fees		ees	-	-				
LTA Search Fee     Medical Fees (on behalf of driver, if applicable)     Overrun		Fees (on behalf	\$7.49/\$2.00					
	narks:							

## CALLOR DELGRO ENGINEERING PTE LID

## REPAIR ESTIMATE®

VEHICLE NO SHA1029L

MAKE REG: 12.05.2016

MODE

29.08..21

MODEL	HYU-140	Type	CHIANG/ AIG		TB		
Qty	Parts Description/ Labour		Unit Price	Amount			
	1 REAR BUMPER COVER		553.00	\$ <del>1,106.0</del> 0			
	10 REAR BUMPER CLIPS		\$2.20	\$22.00			
	REAR BUMPER REFLECTOR /RH			\$32.00	' /		
	IREAR BUMPER UNDER COVER			\$228.00	SCV		
	1	UB TOTAL		\$1,388.00			
		20.00%		\$277.60			
	DISCOUNT	ED TOTAL		\$1,110.40			
					/.		
	1 REAR REVERSE SENSOR			\$135.70			
	1 REAR BUMPER PROTECTOR			\$50.00	SCV		
				\$185.70			
	Labour Charge						
	Panel Beating			\$560.00	280		
	Spray Painting Charge			\$300.00	250		
	Remove/refix reverse sensor			\$60.00	20		
	Tuff Kote			\$60.00	20		
	Check Lighting & Wiring			\$60.00	PO		
	TOTA	L LABOUR		\$1,040.00			
	ESTIMA	TE TOTAL		\$2,336.10			
					]		
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will						

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. Thwan Lth / theran@ Chhauto low 82235769

L/s after repair photos
31/8/21 164630
2days wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: