

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

30-Aug-21

TP China.

Our ref : TP/5023/21

Cecilin.

Heng Seng Lee Electrical & Plumbing Contractor

RE : estimate cost for vehicle no : GBL 350C

1 pc	tailgate <i>Distorted</i>	2,150.00 ✓
1 pc	tailgate logo <i>new</i>	75.00 ✓
1 pc	tailgate Toyota Hiace sticker <i>new</i>	48.00 ✓
1 pc	tailgate lock <i>Damaged</i>	275.00 ✓
2 pcs	tailgate absorber <i>new</i>	710.00 +
1 pc	tailgate rubber <i>new cut</i>	395.00 +
1 pc	tailgate outer handle <i>cut</i>	155.00 ✓
2 pcs	tailgate hinges <i>new</i>	267.60 +
1 pc	tailgate trimboard <i>Distorted</i>	182.00 ✓
1 pc	rear w/screen glass <i>shattered</i>	1,261.34 ✓
1 pc	wiper arm <i>new</i>	59.70 ✓
1 pc	wiper motor <i>new</i>	650.00 +
2 pcs	taillamp <i>LH at, RH could</i>	601.60 ✓
6 pcs	taillamp clips <i>new</i>	33.00 -
2 pcs	rear no plate lamp <i>new</i>	321.60 +
1 pc	rear bumper <i>Distorted</i>	615.00 ✓
1 pc	end panel inner <i>Repair</i>	890.00 +
1 pc	end panel outer <i>Distorted</i>	588.30 ✓
2 pcs	rear bumper retainer <i>new</i>	130.00 ✓
2 pcs	apron panel <i>RH Distorted</i>	200.00 - 100
1 pc	apron panel retainer rh <i>new</i>	45.00 +
4 pcs	rear bumper lower bracket <i>Best</i>	120.00 ✓
6 pcs	rear bumper clips <i>new</i>	30.00 ✓
1 pc	spare tyre tray <i>new</i>	252.50 +
1 pc	spare tyre screw <i>new</i>	30.00 +
1 pc	rear rh fender <i>Repair</i>	1,500.00 +
1 pc	taillamp rh inner panel <i>Repair Distorted</i>	545.00 ✓
<i>Rear End Panel Top Chrome less 25% 175 ✓</i>		12,130.64
<i>Best ✓</i>		3,032.66
		9,097.98
1 pc	70 km/h sticker <i>new</i>	25.00 snett 15
1 pc	rear no plate <i>new</i>	30.00 x-
1 pc	rear w/screen gum <i>new</i>	50.00 ✓
1 pc	reverse sensor <i>Damaged</i>	250.00 - 200
		9,452.98

1855

7249.44

5836.93

Air Duct Distorted ✓ GS

265

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

RE : estimate cost for vehicle no : GBL 350C

Bal brought forward:----- \$ 9,452.98

1 pc rear w/screen seal *Mer*
1 pc wooden board *Not in*
Panel beating.
Spray painting.
Wiring.
Upholstery.
Transfer tailgate fitting.
Remove & refit rear w/screen.

295

2680

30.00	snett	✓
500.00	+	✓
1,800.00	1200	
1,800.00	1200	
30.00	✓	
120.00	50	
80.00	✓	
120.00	✓	
13,932.98		
975.30		
14,908.28		

Plus 7% GST

SD : Fourteen thousand nine hundred eight & cents twenty-eight only.

Adrian L
P/P 30/08/21.

00 Days.

total: 8411.93

C/P/P)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: