

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVE 4
#03-21 S415875

STK AUTO(S) PTE LTD

Email: stkautosg@gmail.com

Contact Person: TAN GUOHUA

HP: 91237949 / 63860669

Date: 30.08.2021

To: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Attn: Motor Claim Department

ESTIMATED REPAIR COST DETAILS

Owner: LUXPERIENCE PTE LTD
Vehicle Number: SMW6794C
Make & Model: AUDI A4
Accident Date: 27.08.2021

C/N	LIST ITEM	QTY	AMOUNT S\$
1	REAR BUMPER <i>Detnd</i>	1	2058 ✓
2	SPOILER <i>Detnd</i>	1	245 ✓
3	REAR BUMPER SPONGE <i>new</i>	1	169 +
4	REAR BUMPER REINFORCEMENT <i>Detnd</i>	1	598 ✓
5	REAR SENSOR <i>Detnd</i>	1	172 ✓
6	REAR BUMPER BRACKETS @141.00 <i>Detnd</i>	2	282 ✓
7	REAR END PANEL <i>Detnd</i>	1	482.16 +
8	REAR END PANEL GARNISH <i>new</i>	1	68.5 +
9	EXHAUST ASSY <i>new</i>	1	1398 +
			5472.66
Less 5% Disc			273.633
Total			5199.027

NETT ITEMS

1	TAILGATE <i>2 new Rys</i>	1	3358 +
	TAILGATE LOCKER STRIKER <i>new</i>	1	125 +
2	REAR BUMPER CLIPS (1SET) <i>new</i>	1	50 <i>30</i>
3	TAILGATE INNER TRIMBOARD CLIPS (1SET) <i>new</i>	1	50 +
4	REAR END PANEL SEALANT <i>new</i>	1	80 +
5	REAR END PANEL GARNISH CLIPS (1SET) <i>new</i>	1	40 +
Total			3703

LABOUR COST

- 1 To remove, cut out damage parts, align, panel beating and renew replace parts.
- 2 To putty and respray painting on affected areas.
- 3 To rewire rear portion
- 4 To remove, fix reverse sensor
- 5 To remove, fix reverse camera
- 6 To tuff kote affected areas.

Total 1900

Grand Total 10802.027

Total: 4099.50
2/s: 3.2K.

Adrian G
30/08/21
1/s 04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: