

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 27/08/2021
TP Veh Reg No: YQ217G

Estimate No: EST2100225
Date: 28 Aug 2021

Veh Reg No: SMC2398U
Make/Model: TOYOTA VIOS E(AUTO)
Chasis No: MR2B23F3501122670
Reg. Date: 28/06/2018
Your Ref No: YQ217G

Xino Tony

Estimate Repair Cost to Vehicle No :SMC2398U

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC BOOT LID <i>Perked</i>	855.50	✓ 765..
2	2 PCS BOOT LID HINGE <i>new Best</i>	170.40	✓
3	1 PC BOOT LID LOGO <i>new</i>	52.20	✓
4	1 PC BOOT LID LAMP LH <i>could</i>	279.80	✓
5	1 PC BOOT LID LAMP RH <i>new</i>	279.80	+
6	1 PC REAR NUMBER PLATE LAMP GARNISH <i>new</i>	130.30	+
7	1 PC BOOT LID RUBBER <i>at</i>	166.40	✓
8	1 PC BOOT LID TRIM <i>new</i>	278.90	+
9	1 PC BOOT LID LOCK <i>changed</i>	320.40	✓ 135
10	1 PC BOOT LID LOCK CHECKER <i>new</i>	38.90	+
11	1 PC REAR PANEL <i>Perked</i>	728.70	✓ 585
12	1 PC REAR PANEL TRIM <i>Perked</i>	242.30	✓
13	1 PC REAR FENDER TRIM RH <i>new could</i>	355.90	✓ 165
14	1 PC REAR FENDER TRIM LH <i>new</i>	355.90	+
15	1 PC SPARE TYRE COVER <i>to</i>	206.90	✓
16	1 PC SPARE TYRE PANEL RH SPONGE <i>new could</i>	244.10	✓
17	1 PC SPARE TYRE PANEL LH SPONGE	244.10	✓
18	1 PC TAIL LAMP LH <i>could</i>	397.10	✓
19	1 PC TAIL LAMP - RH <i>could</i>	397.10	✓
20	1 PC REAR BUMPER <i>Perked</i>	482.20	✓
21	1 PC REAR BUMPER REINFORCEMENT <i>Perked</i>	316.10	✓
22	2 PCS REAR BUMPER SIDE RETAINER <i>new</i>	287.00	✓ 82
23	2 PCS REAR BUMPER RETAINER (SMALL) <i>new</i>	145.40	✓
24	1 PC REAR BUMPER REFLECTOR - RH <i>could</i>	92.80	✓
	<i>1pc 4 antenna sensor 156.70</i>	7.068.20	
		Less 25%	1,767.05
			5,301.22
	Special Net		
25	1 PC BOOT LID NUMBER '613' STICKER <i>new</i>	35.00	✓
26	1 PC REAR NUMBER PLATE <i>new</i>	50.00	+

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 27/08/2021
TP Veh Reg No: YQ217G

Estimate No: EST2100225
Date: 28 Aug 2021

Veh Reg No: SMC2398U
Make/Model: TOYOTA VIOS E(AUTO)
Chasis No: MR2B23F3501122670
Reg. Date: 28/06/2018
Your Ref No: YQ217G

Estimate Repair Cost to Vehicle No :SMC2398U

Quantity	Description	List Price	Amount
		SS	SS
27	1 SET BOOTLID TRIM CLIPS <i>mean</i>	40.00 <i>x</i>	
28	1 SET REAR PANEL TRIM CLIPS <i>mean</i>	40.00 <i>20</i>	
29	1 SET REAR FENDER TRIM CLIPS RH <i>mean</i>	40.00 <i>+</i>	
30	1 SET REAR FENDER TRIM CLIPS LH <i>mean</i>	40.00 <i>+</i>	
31	1 SET REAR BUMPER STICKER <i>mean</i>	280.00 <i>200</i>	
32	2 PCS "L" PLATE BRACKET <i>mean</i>	70.00 <i>50</i>	
33	1 SET REAR BUMPER CLIPS <i>mean</i>	40.00 <i>30</i>	
		635.00	635.00
	Labour		
34	1 TO CHECK WIRING	50.00 <i>30</i>	
35	1 TO REPLACE STICKERS	80.00 <i>x</i>	
36	1 TO SPRAY UNDERSEAL	80.00 <i>60</i>	
37	1 (REAR) TO SPRAY PAINTING	1,200.00 <i>850</i>	
38	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,200.00 <i>800</i>	
	<i>To remove upholstery</i>	2,610.00	2,610.00
	<i>To transfer bootlid fittings</i>		
	<i>Adnan</i>	Total	S\$ 8,546.22
	<i>150 4/s 30/08/21</i>	Add GST @ 7%	598.24
	<i>80, 06 Days</i>	Total Amount Payable	S\$ 9,144.46

TOTAL: SINGAPORE DOLLAR NINE THOUSAND ONE HUNDRED FORTY FOUR AND CENTS

LKK Auto Consultants hereby notify the Repairer of the following:

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

- To resurvey the vehicle for further damage
- To display damaged part(s) during repair
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE