

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 27/08/2021
TP Veh Reg No: YQ217G

Estimate No: EST2100225

Date: 28 Aug 2021

Veh Reg No: **SMC2398U**
Make/Model: TOYOTA VIOS E(AUTO)
Chasis No: MR2B23F3501122670
Reg. Date: 28/06/2018
Your Ref No: YQ217G

Estimate Repair Cost to Vehicle No :SMC2398U

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	List Price		
1	1 PC BOOT LID	855.50	
2	2 PCS BOOT LID HINGE	170.40	
3	1 PC BOOT LID LOGO	52.20	
4	1 PC BOOT LID LAMP LH	279.80	
5	1 PC BOOT LID LAMP RH	279.80	
6	1 PC REAR NUMBER PLATE LAMP GARNISH	130.30	
7	1 PC BOOT LID RUBBER	166.40	
8	1 PC BOOT LID TRIM	278.90	
9	1 PC BOOT LID LOCK	320.40	
10	1 PC BOOT LID LOCK CHECKER	38.90	
11	1 PC REAR PANEL	728.70	
12	1 PC REAR PANEL TRIM	242.30	
13	1 PC REAR FENDER TRIM RH	355.90	
14	1 PC REAR FENDER TRIM LH	355.90	
15	1 PC SPARE TYRE COVER	206.90	
16	1 PC SPARE TYRE PANEL RH SPONGE	244.10	
17	1 PC SPARE TYRE PANEL LH SPONGE	244.10	
18	1 PC TAIL LAMP LH	397.10	
19	1 PC TAIL LAMP - RH	397.10	
20	1 PC REAR BUMPER	482.20	
21	1 PC REAR BUMPER REINFORCEMENT	316.10	
22	2 PCS REAR BUMPER SIDE RETAINER	287.00	
23	2 PCS REAR BUMPER RETAINER (SMALL)	145.40	
24	1 PC REAR BUMPER REFLECTOR - RH	92.80	
		7,068.20	
	Less 25%	1,767.05	5,301.22
	Special Net		
25	1 PC BOOT LID NUMBER '613' STICKER	35.00	
26	1 PC REAR NUMBER PLATE	50.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 27/08/2021
TP Veh Reg No: YQ217G

Estimate No: EST2100225
Date: 28 Aug 2021

Veh Reg No: **SMC2398U**
Make/Model: TOYOTA VIOS E(AUTO)
Chasis No: MR2B23F3501122670
Reg. Date: 28/06/2018
Your Ref No: YQ217G

Estimate Repair Cost to Vehicle No :SMC2398U

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
27	1 SET BOOTLID TRIM CLIPS	40.00	
28	1 SET REAR PANEL TRIM CLIPS	40.00	
29	1 SET REAR FENDER TRIM CLIPS RH	40.00	
30	1 SET REAR FENDER TRIM CLIPS LH	40.00	
31	1 SET REAR BUMPER STICKER	280.00	
32	2 PCS "L" PLATE BRACKET	70.00	
33	1 SET REAR BUMPER CLIPS	40.00	
		<u>635.00</u>	635.00
	Labour		
34	1 TO CHECK WIRING	50.00	
35	1 TO REPLACE STICKERS	80.00	
36	1 TO SPRAY UNDERSEAL	80.00	
37	1 (REAR) TO SPRAY PAINTING	1,200.00	
38	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,200.00	
		<u>2,610.00</u>	2,610.00
		Total	S\$ 8,546.22
		Add GST @ 7%	598.24
		Total Amount Payable	<u>S\$ 9,144.46</u>

TOTAL: SINGAPORE DOLLAR NINE THOUSAND ONE HUNDRED FORTY FOUR AND CENTS FORTY SIX ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE