

FIRST AUTOWORKS

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 26/8/2021

Reference: SGG 9555L

Make: BMW
740li

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SGG 9555L
CHASSIS NO.: WBAYE42090DD87097
ENGINE NO.: 11628262N55B30A

T? ALG.
Xiao Tong.

Name of insured : Pang Hwee Mui

Date of accident.: 21/08/2021

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts FRONT

No.	Qty	Part Description	Price (SGD)
1	1	FRONT BUMPER <i>Repair</i>	2153.00 X
2	1	RHS BUMPER CAMERA <i>Not Nec</i>	980.00 X
3	1	RHF RIM <i>Not Nec Repair cut</i>	1450.00 X <i>100(SN)</i>
4	1	TIRE PRESSURE SENSOR <i>Not Nec</i>	700.00 X

Parts Total: 5283.00
Less 10%: 528.30
Total : 4754.70

Labour No.

Labour Description

Price (SGD)

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	1400.00 <i>250</i>
2	Carry out spray painting on accident affected area.	800.00 <i>250</i>
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	80.00 <i>30</i>
4	Remove & refit Tire	50.00 X
5	To remove and refit frt sensor and conduct test	180.00 <i>60</i>
6	To remove and refit camera and conduct test	180.00 <i>60</i>
7	To conduct 4 wheel alignment.	150.00 <i>90</i>

Labour Total : 2690.00

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Next to Vicom Building, Singapore 415933 Tel : 6844 1985 Fax : 6844 5185

Others

<u>No.</u>	<u>Qty</u>	<u>Other Description</u>	<u>Price (SGD)</u>
1	1	Frt bumper Clipset <i>Not rec Nkr</i> 30	80.00 <i>30</i>
Other Total:			80.00

Total : \$7,524.70
Gst (7%) : \$526.73
GRAND TOTAL: \$8,051.43

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully



Service Adviser
Ronnie Tan
HP : 8298 8933 Fax:6844 5185

*Adrian Ling
P/P 30/08/21.*

03 Days.

total: 870 (P/P)

<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none">• To resurvey before/after spray painting• To display damaged part(s) during resurvey• Parts prices are subject to confirmation• Third party survey is on a "Without Prejudice" basis• No illegal modification(s) is allowed• Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from insurance Company <p>Acknowledged by Repairer Signature: _____ Date: _____</p>
--