

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

TAX INVOICE

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way
#07-16, Singapore 079120

GST Ref. No: 20-0000274-Z

Vehicle No: ::SGG 9555L
Chasis No : WBAYE42090DD87097
Engine No: 11628262N55B30A

Invoice No: CGI-ASC-22IR00282G

Invoice Date: 11/2/2022

DESCRIPTION	AMOUNT SGD
-------------	---------------

Labour

<u>No.</u>	<u>Description</u>	<u>Price (SGD)</u>
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	250.00
2	Carry out spray painting on accident affected area	350.00
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	30.00
4	To remove and refix frt sensor and conduct test	60.00
5	To remove and refix reverse camera and conduct test	60.00
6	To conduct 4 wheel alignment	90.00

Labour Total : 840.00

Other

<u>No.</u>	<u>Other Description</u>	<u>Price (SGD)</u>
1	1 Frt bumper clip Set	30.00

Other Total : 30.00

Total : \$870.00
GST (7%) \$60.90
Grand Total: \$930.90

Yours Faithfully,



Ronnie Tan
Service Advisor
Tel: 68441985 Fax: 68445185

E & O E

- ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "1ST Autoworks Pte Ltd".
- PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.