



CHENG HOE MOTOR PTE LTD

Bik 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761
Tel : 67556142 Fax : 67557719
Email: chmotor@singnet.com.sg

TP INSURER:
GAN SER LENG

Singapore

China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

Claimant Insurer:

China Taiping Insurance (Singapore) Pte. Ltd.

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP/CHINA (SJL9146Y)
Policy No:	DMPCSNW00187292000	Date of Loss:	27/08/2021
Vehicle Reg. No.:	SBN6888T	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	YONG POH LING (YANG BAOLING)		
Make/Model:	TOYOTA ESTIMA, 2.4 AERAS (A)	Vehicle Reg. Date:	10/05/2013
Vehicle Colour:	GREY	Chassis No:	ACR507116529
Engine No:	2AZH971028		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	REFER TO STATEMENT		
Present Location:	CHENG HOE MOTOR PTE LTD (AMK)		

*Not Authorized
L1Rn & 2600h
Repair the Paint
today*

COST OF CLAIMS

Parts	Amount
Miscellaneous Items	1,407.50
Labour	320.00
Paintwork Labour	1,830.00
Towing	0.00
	0.00

Gross Total (S\$)	3,557.50
+ GST 7.00% (S\$)	249.03
Nett Amount (S\$)	3,806.53

This claim is handled by: DORLYN LI YAZHU

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Version: 1.0 (Last Synchronised: 12 Oct 2021)
M1-MPV TOYOTA ESTIMA 2.4 AERAS (A) (Catalogue:Merimen Singapore 1.0)
Repairer's (Price-denominated Standard List)
Print Code: **Cheng Hoe Motor Pte Ltd/SBN6888T/12/10/2021 10:41**
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 pc rear bumper			
2	1		*5 pcs rear bumper clips @ \$1.50/pc			
3	1		*1 pc tailgate	0.00	0.00	*280.00 F
4	1		*1 pc tailgate inner rubber	0.00	0.00	*7.50 F
5	1		*1 pc tailgate inner lock outer cover	0.00	0.00	*600.00 F
6	1		*1 pc tailgate logo	0.00	0.00	*125.00 F
7	1		*1 pc tailgate emblem Estima	0.00	0.00	*24.00 F
8	1		*1 pc tailgate emblem Aeras	0.00	0.00	*25.00 F
9	1		*1 set tailgate windscreen glass moulding	0.00	0.00	*28.00 F
10	1		*1 pc rear end panel	0.00	0.00	*50.00 F
Total Parts (S\$)						1,407.50

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	1 set reverse sensors (4pcs)	280.00
2	1	1 unit rear windscreen glass sealant	40.00
Sub Total (S\$)			320.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Remove & refix rear windscreen glass	New	120.00
2	Remove & refix rear bumper & parking sensors, tailgate & attachments; to cut, weld & renew rear end panel; knocking & repair rear luggage panel & realign the same	New	700.00
3	Putty & respray rear bumper & parking sensors, tailgate, rear end panel, rear luggage panel & all affected areas	New	800.00
4	Remove & refix reverse camera, reset & realign the same	New	50.00
5	Remove & refix rear seats, garnish to facilitate repair	New	100.00
6	Rustproofing	New	60.00
Gross Labour Cost (S\$)			1,830.00

Cheng Hoe Motor Pte Ltd/SBN6888T/12/10/2021 10:41. Not valid without Reference section.
Generated using Merimen e-Claims IEAS
< END OF ESTIMATES >