

⏪	<	1 of 2 ?	>	⏩	↺	↻	100% ▼	🖨	📄	Find Next
---	---	----------	---	---	---	---	--------	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD		Ref: CS/MSG21009171/Etf3		
4 SHENTON WAY #21-01,SGX CENTRE 2		Date: 01/09/2021		
SINGAPORE 068807		Code: MSG		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	FBB 3741R	Veh. Inspected	FU 7232U	
Policy No.	MSD/VM/20-413955	Coverage (\$)	0.00	
Claim No.	MSC/V/21-000396	Excess (\$)	0.00	
Assign From	MERIMEN (DOUGLAS ONG CHU CHONG)	Assign Date	01/09/2021	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	29/08/2021	Inspection Date	01/09/2021	
Survey held at	3POINTS ENTERPRISE 50 BUKIT BATOK STREET 23, #02-22, MIDVIW BUILDING, SINGAPORE 659578			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				