

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0563/2021/JT
DATE : 7-Jul-21
WIP : 34338

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY ON 9/7/2021

YOUR INSURED VEH NO :SJE 8785 X

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

3 days

Johnny Boo 5 Oct 21

OWNER'S NAME : MR HENG CHIANG YONG
ADDRESS : 758 BEDOK RESERVOIR ROAD
#12-22
SINGAPORE 479260
TELEPHONE : HP +65 9641 3228
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700037768-03
VEHICLE NO : **SJE 8785 X**
MODEL CODE : A3 SEDAN 1.0 TFSI
MODEL YEAR : 8/10/2017
ENGINE NO : CHZ 508444
CHASSIS NO : WAUZZZ8VXJ1004664
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 6-Jul-21
PLACE OF ACCIDENT : NEAR 122 BEDOK NORTH AVE 1,
ALONG BEDOK NORTH , NEAR MOSQUE

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJE 8785 X

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION.	S/N \$	280.00	\$ 280.00
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,050.00	\$ 500.00
3	TO RESPRAY REAR BUMPER.	\$	900.00	\$ 550.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$	2,422.00	\$ 1,522.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 9102 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 1,944.00	
2	REAR BUMPER FIXING PARTS	1	\$ 193.00	
3	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 32.00	
4	REAR BUMPER SPOILER	1	\$ 237.00	\$ 189.60
5	REAR BUMPER REFLECTOR - LH	1	\$ 41.00	
6	REAR BUMPER PARKING AID SENSOR	2	TBC	
7	REAR BUMPER PARKING AID SENSOR SEAL RING	4	\$ 14.00	
8	REAR BUMPER REINFORCEMENT	1	\$ 603.00	
9	REAR BUMPER BRACKET - LH / RH	2	\$ 56.00	
10	SUNDRIES		\$ 250.00	
TOTAL SPARE PARTS		:	\$ 3,370.00	\$ 189.60
TOTAL LABOUR CHARGES		:	\$ 2,422.00	\$ 1,522.00
GRAND TOTAL		:	\$ 5,792.00	\$ 1,711.60

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-29/09/21

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.

FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT