



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

HSBC LIFE (SINGAPORE) PTE LTD
10 MARINA BOULEVARD
#48-01 MARINA BAY FINANCIAL CENTRE TOWER
2SINGAPORE 018983
ATTN:KITTY

Ref: CC4/ASM21009183/Gpa3q2

Date: 04/05/2023

Code: HSB

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	EL 44B	Veh. Inspected	SJX 4222E
Policy No.	GA570988	Coverage (\$)	0.00
Claim No.	S1M03GT0	Excess (\$)	0.00
Assign From		Assign Date	01/09/2021

2. Vehicle Particulars & Condition

Make & Model	SUBARU FORESTER 2.0I	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JF1SJ5KC5JG111818	Colour	WHITE
Odometer	26911 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/60 R17	YOKOHAMA	6 mm
L/H Front Tyre	225/60 R17	YOKOHAMA	6 mm
R/H Rear Tyre	225/60 R17	YOKOHAMA	6 mm
L/H Rear Tyre	225/60 R17	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/08/2021	Inspection Date	02/09/2021
Survey held at	56 LOYANG WAY, #04-04 LOYANG ENTERPRISE BUILDING		
Repairer	AP AUTOMOTIVE SERVICES PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**