

AP Automotive Services

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Estimation
 Acknowledged by Repairer
 Signature: _____ Date _____
 Date: _____ Vehicle _____

AP AUTOMOTIVE SERVICES PTE LTD
 ROC: 202022890H
 BLOCK 9006
 TEMPINES STREET 93 #01-202
 SINGAPORE 528840
 TEL: 6784 4465
 FAX: 6787 4886

SJX 4222 E
 SUBARU FORESTER
 JF1S15KC5JG111818

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	TAILGATE / Bmc	1	\$ 1072.80	✓ -
2	TAILGATE OUTER / ? / BR	1	\$ 160.80	✓ -
3	TAILGATE LOGO - SUBARU / ? / MCL	1	\$ 88.10	✓ -
4	TAILGATE EMBLEM - SUBARU / MCL	1	\$ 72.10	✓ -
5	TAILGATE EMBLEM / X / NN	1	\$ 82.20	-
6	TAILGATE EMBLEM - AWD /	1	\$ 72.10	✓ -
7	TAILGATE EMBLEM - FORESTER / MCL	1	\$ 78.20	✓ -
8	TAILGATE EMBLEM - SPORT /	1	\$ 400.30	✓ -
9	TAILGATE LOCK / CA	1	\$ 176.40	✓ -
10	TAILGATE LOCK CATCH / X / NN	1	\$ 34.10	-
11	TAILGATE INNER TRIM / ? / BR	1	\$ 180.20	✓ -
12	TAILGATE STOPPER SET / X /	1	\$ 18.40	-
13	TAILGATE HINGE SET / X /	1	\$ 88.20 / 176.40	-
14	TAILGATE DAMPER SET / X / NN	1	\$ 26.50	-
15	TAILGATE WEATHERSTRIP / ? / Cut	1	\$ 142.40	\$ 142.40 ✓ X S/N.
16	TAIL LAMP L+R / ? / Cut	2	\$ 493.75	\$ 987.50 ✓ 900
17	TAIL LAMP LOWER BRACKET L+R / LH / ? / BR	2	\$ 67.80	\$ 135.60 ✓ 57
18	TAIL LAMP PANEL L+R / X / NN / PH / CRA	2	\$ 89.15	\$ 178.30
19	REAR BUMPER /	1	\$ 631.50	\$ 631.50 ✓ 540.3
20	REAR BUMPER REVERSE SENSOR SET / DM	2	\$ 234.10	\$ 468.20 ✓ 200 (S/N) ✓
21	REAR BUMPER TOW COVER / X /	1	\$ 631.50	\$ 631.50
22	REAR BUMPER REFLECTOR L+R / ? / BR	2	\$ 79.80	\$ 159.60 ✓ 45.6
23	REAR BUMPER LOWER DIFFUSOR / CRA	1	\$	\$ 1200.30 ✓
24	REAR BUMPER RETAINER L+R / LH / X / NN / PH / Cut	2	\$ 94.30	\$ 188.60 ✓ 27
25	REAR BUMPER REINFORCEMENT BAR / ? / BT	1	\$	\$ 320.10 ✓ 288
26	REAR BUMPER SPONGE / X / NN	1	\$ 105.80	\$ 105.80
27	REAR BUMPER UNDERCOVER / X /	1	\$	\$ 267.20
28	REAR FENDER L+R / X / NN	2	\$ 1,134.60	\$ 2,269.20
29	REAR FENDER INNER TRIM L+R / X /	2	\$ 600	\$ 1200 -
30	REAR FENDER COWLING L+R / ? / LH / X / NN / PH / TV	2	\$ 121.45	\$ 242.90 ✓
31	END PANEL / ? / Bmc	1	\$ 351.70	\$ 351.70 ✓ 332
32	END PANEL TOP GARNISH / ? / ee	1	\$ 291.80	\$ 291.80 ✓ 140, 729 90
33	SPAREWHEEL PANEL / ? / Bmc	1	\$	\$ 822.80 ✓
34	SPAREWHEEL PANEL TOP BOARD / ? / Cut	1	\$	\$ 320.10 ✓
35	SPAREWHEEL INNER SPONGE CENTER / ? /	1	\$	\$ 153.10 ✓
36	SPAREWHEEL INNER SPONGE L+R / ? / CRA	2	\$	\$ 72.10 ✓
37	EXHAUST PIPE / X / NN	1	\$	\$ 668.20

6772.65

-20%: 5418.12

38	EXHAUST HEAT SHIELD X NN	1		\$ 321.00	
			Total	\$ 14,050.90	5,998.70
			Less 10%	\$ 1,405.09	599.87
			Total	\$ 12,645.81	5,398.83

13,167.10
12,269.70

S/Nett Items					
1	TAILGATE WINDSCREEN SEALANT / MGC	1	100	\$ 100.00	40
2	TAILGATE INNER TRIM CLIPS / MGC	1	100	\$ 100.00	30
3	TAIL LAMP CLIP SET / MGC	1	50	\$ 50.00	20
4	TAIL LAMP PANEL SEALANT X NN	1	80	\$ 80.00	
5	REAR NUMBER PLATE / MGC	1	120	\$ 120.00	40
6	REVERSE CAMERA X NN	1	800	\$ 800.00	
7	REAR BUMPER CLIP SET / MGC	1	100	\$ 100.00	40
8	REAR BUMPER TOP PLATE / BT	1	600	\$ 600.00	150
9	REAR FENDER SEALANT X	2	250	\$ 500.00	
10	REAR FENDER WINDOW SEALANT X NN	1	80	\$ 80.00	
11	REAR FENDER COWLING CLIP SET / MGC	2	100	\$ 200.00	
12	END PANEL SEALANT / MGC	1	200	\$ 200.00	40
13	END PANEL TOP GARNISH CLIP SET / MGC	1	100	\$ 100.00	
14	SPAREWHEEL PANEL SEALANT X NN	1	250	\$ 250.00	
15	AUTO TAILGATE MODULE CONTROL X NN			\$ 3,000.00	
16	AUTO TAILGATE ABSORBER X NN			\$ 3,000.00	
			Total	\$ 9774.70	2,830.00

LABOUR					
1	PANEL BEATING ON AFFECTED AREAS	1	2400	\$ 1000.00	2,400.00
2	SPRAY PAINT ON AFFECTED AREAS	1	1800	\$ 800.00	1,800.00
3	TO RNR REAR WINDSCREEN	1	400	\$ 400.00	400.00
4	TO BREAK SEAL FOR OFF PEAK VEHICLE	1	300	\$ 300.00	300.00
5	TO RNR REAR EXHAUST	1	250	\$ 250.00	250.00
6	TO RNR REAR FENDER WINDOW	1	350	\$ 350.00	350.00
7	TO CHECK WIRING AND TAIL LAMP FUNCTION	1	150	\$ 150.00	150.00
8	TO CHECK WIRING AND TAILGATE LAMP FUNCTION	1	150	\$ 150.00	150.00
9	TO RNR REAR INNER TRIM AND UPHOISTERY	1	400	\$ 400.00	400.00
10	TO CHECK WHEEL ALIGNMENT AND ADJUST	1	250	\$ 250.00	250.00
11	TO RNR UNDERCARRIAGE	1	250	\$ 250.00	250.00
12	TO CHECK WATER LEAK	1	150	\$ 150.00	150.00
13	TO RNR FUEL TANK	1	250	\$ 250.00	250.00
14	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	1	800	\$ 800.00	800.00
15	TO RNR REAR TAILGATE MECHANISM	1	400	\$ 400.00	400.00
16	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	1	150	\$ 150.00	150.00
17	TO PERFORM RUST PROOFING	1	400	\$ 400.00	400.00

Total Labour	\$ 8,850.00
Parts Replacement Amount	\$ 8,228.83
Total Amount	\$ 17,078.83

7928.12
-20%: 6300

6
Days.
4/5 repair
After repair photos.
Gma Qiap
02/5/2021