

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
--	---

Attn: Elaine Ngu Siau Mei

Date: 13 Sep 2021

Preliminary Advice

Insured	: YN921Y		
Vehicle No			
TP Vehicle No	: EH3737L	Accident Date	: 31/08/2021
Make	: TOYOTA COROLLA ALTIS	Assignment Date	: 03/09/2021
Date of Inspection	: 01/09/2021	Est. Duration of Repair	: 4
Inspection At	: FASTECH AUTO PTE LTD (HQ) 1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,819.40
Revised Amount	:S\$	4,501.79
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,501.79

Lump Sum Repair	:S\$	3,600.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$

Salvage Value :S\$

Margin for Repair :S\$

Remarks

() The vehicle is economical for repair

() The vehicle is not economical for repair

() Part-by-Part repair

(X) Lump Sum repair

(X) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advice amount (Revised & Check Items)
stated are subject to consistency check, part prices and labour cost.