

**Estimation**

Date  
 Vehicle  
 Make/Model  
 Chassis No.

SGQ 1706 T  
 HONDA JAZZ  
 JHMGD185075202802

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	BONNET X	1	\$	-
2	BONNET LOCK X	1	\$	-
3	BONNET LOCK CATCH X	1	\$	-
4	BONNET HINGE X	2	\$	-
5	HEADLAMP L+R X	2	\$	-
6	HEADLAMP BRACKET L+R X	2	\$	-
7	FRONT GRILLE X	1	\$	-
8	FRONT GRILLE LOGO - HONDA X	1	\$	-
9	FRONT BUMPER	1	\$	-
10	FRONT BUMPER GRILLE X	1	\$	-
11	FRONT BUMPER RETAINER L+R	2	\$	-
12	FRONT BUMPER REINFORCEMENT BAR X	1	\$	-
13	FRONT BUMPER SPONGE X	1	\$	-
14	FRONT FENDER LH	1	\$	-
15	FRONT FENDER INNER PANEL LH X	1	\$	-
16	FRONT FENDER QUARTER WINDOW WITH MOULDING LH	1	\$	-
17	FRONT FENDER COWLING LH	1	\$	-
18	FRONT SUPPORT PANEL X	1	\$	-
19	FRONT SUPPORT PANEL TOP GARNISH X	1	\$	-
20	A PILLAR LH X	1	\$	-
21	FRONT DOOR LH X	1	\$	-
22	FRONT DOOR SIDE MIRROR ASSY LH X	1	\$	-
23	FRONT DOOR SIDE MIRROR COVER LH X	1	\$	-
24	FRONT DOOR WEATHERSTRIP LH X	1	\$	-
25	FRONT DOOR INNER WEATHERSTRIP LH X	1	\$	-
26	ROCKER PANEL LH X	1	\$	-
27	WIPER WASHER TANK X	1	\$	-
28	FRONT ABSORBER LH X	1	\$	-
29	FRONT LOWER ARM LH X	1	\$	-
30	FRONT KNUCKLE LH X	1	\$	-
31	FRONT KNUCKLE BEARING LH	1	\$	-
32	FRONT BEARING HUB LH X	1	\$	-
33	FRONT DRIVE SHAFT LH X	1	\$	-
34	FRONT TIE ROD LH X	1	\$	-
35	FRONT TIE ROD END LH X	1	\$	-
36	FRONT STABILIZER LINK LH X	1	\$	-
			Total	\$

		Less 20%	\$	-
		<b>Total</b>	\$	-

S/Nett Items				
1	FRONT BUMPER CLIPS	✓	100	\$ 100.00
2	FRONT FENDER INNER PANEL SEALANT	X	150	\$ 150.00
3	FRONT FENDER QUARTER WINDOW SEALANT	X	120	\$ 120.00
4	FRONT FENDER COWLING CLIPS	✓	100	\$ 100.00
5	FRONT SUPPORT PANEL TOP GARNISH CLIPS	X	100	\$ 100.00
6	FRONT DOOR INNER BOARD CLIPS	X	100	\$ 100.00
7	ROCKER PANEL SEALANT	X	200	\$ 200.00
8	FRONT RIM LH	cut	100	\$ 100.00
9	FRONT TYRE LH	X	400	\$ 400.00
			<b>Total</b>	\$ <b>1,370.00</b>

LABOUR				
1	PANEL BEATING ON AFFECTED AREAS		1800	\$ 1,800.00
2	SPRAY PAINT ON AFFECTED AREAS		1400	\$ 1,400.00
3	TO CHECK WIRING AND HEADLAMP FOCUS		150	\$ 150.00
4	TO RNR INNER TRIMS AND UPHOISTERY		600	\$ 600.00
5	TO CHECK WHEEL ALIGNMENT AND ADJUST		250	\$ 250.00
6	TO RNR UNDERCARRIAGE		250	\$ 250.00
7	TO CHECK WHEEL BALANCING		250	\$ 250.00
8	TO RNR FRONT AIR CON CONDENSOR AND TOP UP GAS		300	\$ 300.00
9	TO RNR FRONT RADIATOR		250	\$ 250.00
10	TO CHECK WATER LEAK		150	\$ 150.00
11	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS		600	\$ 600.00
12	TO PERFORM RUST PROOFING		400	\$ 400.00
13	TO RNR FRONT DOOR MECHANISM		300	\$ 300.00

400  
 1400  
 20  
 X 60  
 7  
 X  
 X }  
 X }  
 60  
 X

<b>Total Labour</b>	\$	<b>6,700.00</b>
<b>Parts Replacement Amount</b>	\$	<b>1,370.00</b>
<b>Total Amount</b>	\$	<b>8,070.00</b>

5 Days  
 4s  
 After repair photos  
 Enclosed  
 1/9/21

**LKK Auto Consultants** hence notify the Repairer of the following:
 

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

 Acknowledged by Repairer  
 Signature:  
 Date: