

**GOLD PERFORMANCE PTE LTD**

Block 5033 Ang Mo Kio Industrial Park 2 #01-251/259

Singapore 569536

Mobile : 97289234

Email : goldperformancepl@gmail.com

UEN & GST Registration no:202039762K

31.08.2021**QUOTATION****Q:20210801**

Attention: Mr Marvin Chia
cc: Vehicle Owner - Mr Tan Beng Yong

Email:marvin.chia@mclarens.com

Dear Sirs

ESTIMATE REPAIR COST OF SJL8198D (NISSAN TEANA 200XL) MODEL WJ32 on an accident on 27.08.2021 at about 6pm on the premise of Takeda Manufacturing Singapore Pte Ltd, located at 2A Woodlands Industrial Park D, Street 2 Singapore 737779 (during excavation work by Boustead Sub-Contractors)

Item	Description	Qty	Unit Price:S\$	Total:S\$
	To supply labour:-			
01	To knock/repair front bonnet and rooftop			180.00
02	To spray paint front bonnet, rooftop and all affected areas			650.00
03	Front WindScreen	1 pc	1,452.00	1,452.00
03 (a)	Front WindScreen Top Moulding	1 pc	49.06	49.06
03 (b)	WindScreen Gum / Sealant	1 set	44.00	44.00
03 (c)	Labour charges to remove and install WindScreen			150.00
04	Loss of Use, Car Rental - 4 days	4 days	120.00	480.00
				\$ 3,005.06

We hope that our quotation will meet with your kind approval.

Thank you.

.....
Steven Ko
97289234