

KIM SENG TECK MOTOR WORKS

Blk 3021 A Ubi Road 1 #01-42

Singapore 408715

Tel No. : 6741 5520 / 6741 1339 Fax No. : 6741 5808

E-Mail : kimsengteck_motorworks@yahoo.com.sg

Website : kstteam@singnet.com.sg

Tax Reg. No. : M9-0002075-E Buss. Reg. No. : 27157400/C

AIG ASIA PACIFIC INSURANCE PTE LTD

78 Shenton Way #07 - 16

079120

Attention : Motor Claim Department

Tax Invoice : CI200789

Date : 31/08/2021

Vehicle Num. : GBF 635M

Make/Model : Toyota Hiace Van Turbo 5 DR-10 / 06

Chassis/Eng# : JTFHT02P000197960/1KD2619760

Accident Date : 26/08/2021

Claim No. :

Reference :

Policy No. : 999993603

S/N	Quantity	Particular	Unit Price	Amount S\$
after plus 10%				
1.	2	LIST ITEMS :		
2.	1	Front headlamp ✓ <i>RLH - RR (supp) 310</i>	341.00	682.00
3.	1	Front door ✓		748.00
4.	1	Front fender ✓ <i>RLC (supp) 80</i>		88.00
5.	1	Front bonnet ✓		297.00
6.	1	Front bumper ✓		242.00
7.	1	Front grille (top) ✓ <i>RLZ (supp) 130</i>		132.00
8.	1	Front grille lower panel ✓ <i>RLZ (supp) 150</i>		165.00
9.	2	Front grille ✓		275.00
10.	1	Bumper retainers ✓	77.00	154.00
11.	1	Front panel ✓ <i>BT (supp) 40</i>		44.00
12.	1	Front door weatherstrip (inner) ✓ <i>RLC (supp) 120</i>		132.00
13.	1	Front door glass rubber ✓ <i>RLC (supp) 60</i>		66.00
14.	1	Inter Cooler ✓ <i>BT (supp) 600</i>		660.00
15.	1	Door check ✓ <i>BT (supp) 80</i>		88.00
16.	1	Front bonnet cable ✓ <i>RLC (supp) 55</i>		60.50
17.	1	Front bonnet lock ✓ <i>BT (supp) 70</i>		77.00
18.	1	Front door glass ✓ <i>RLC (supp) 170</i>		253.00
19.	1	Front door rubber ✓ <i>RLC (supp) 170</i>		187.00
20.	1	Door pillar ✓		165.00
21.	2	Wiper link ✓ <i>RLC (supp) 250</i>		275.00
22.	1	Door hinge ✓ <i>RLC (supp) 110</i>	60.50	121.00
23.	1	Door inner lock ✓ <i>RLC (supp) 240</i>		242.00
24.	1	Front LH pillar out ✓ <i>RLC (supp) 60</i>		264.00
		Panel LH cowl top ✓ <i>RLC (supp) 60</i>		66.00

CONTINUE / ...

KIM SENG TECK MOTOR WORKS

Blk 3021 A Ubi Road 1 #01-42

Singapore 408715

Tel No. : 6741 5520 / 6741 1339 Fax No. : 6741 5808

E-Mail : kimsengteck_motorworks@yahoo.com.sg

Website : kstteam@singnet.com.sg

Tax Reg. No. : M9-0002075-E Buss. Reg. No. : 27157400/C

AIG ASIA PACIFIC INSURANCE PTE LTD

78 Shenton Way #07 - 16

079120

Attention : Motor Claim Department

Tax Invoice : CI200789

Date : 31/08/2021

Vehicle Num. : GBF 635M

Make/Model : Toyota Hiace Van Turbo 5 DR-10 / 06

Chassis/Eng# : JTFHT02P000197960/1KD2619760

Accident Date : 26/08/2021

Claim No. :

Reference :

Policy No. : 999993603

S/N	Quantity	Particular	Unit Price	Amount S\$
25.	1	Headlamp mtg bracket / BR (Supp) 50		55.00
26.	1	Door striker / BT (Supp) 35		38.50
27.	1	front bumper Grille LH / mis (Supp) 40		44.00
28.	1	Front door suduff plate LH / BT (Supp) 130		143.00
29.	1	Headlamp bracket / BR (Supp) 15		16.50
30.	2	Front bonnet hinges / BT (Supp) 80	44.00	88.00
31.	1	Front door regulator / SBT (Supp) 120		132.00
32.	1	Radiator Assy ✓		770.00
33.	1	Side mirror ✓		220.00
34.	1	Radiator spare tank / SDR (Supp) 180		198.00
35.	1	Wiper tank / 60		66.00
36.	1	Support panel / buc (Supp) 180		198.00
37.	1	Radiator fan cowling / RL (Supp) 140		154.00
38.	1	Emblem / RL (Supp) 40		44.00
39.	1	Front door cardboard ✓ DE - SUPP 400		440.00
40.	1	Front windscreen glass ✓		198.00
41.	2	Silicone seal ✓	11.00	22.00
42.	2	Silicone seal ✓	13.20	26.40
43.	6	clip / NCL (Supp) 18	3.30	19.80
44.	1	Front number plate ✓		12.10
45.	1	Rear lamp (LH) ✓		55.00
46.	1	Air Con Coil ✓		2,530.00
47.	1	Air con condenser ✓		
48.	1	Air con blow system ✓		
List Total S\$:				10,953.80 ✓

CONTINUE / ...

KIM SENG TECK MOTOR WORKS

Blk 3021 A Ubi Road 1 #01-42

Singapore 408715

Tel No. : 6741 5520 / 6741 1339 Fax No. : 6741 5808

E-Mail : kimsengteck_motorworks@yahoo.com.sg

Website : kstteam@singnet.com.sg

Tax Reg. No. : M9-0002075-E Buss. Reg. No. : 27157400/C

AIG ASIA PACIFIC INSURANCE PTE LTD

78 Shenton Way #07 - 16

079120

Attention : Motor Claim Department

Tax Invoice : CI200789

Date : 31/08/2021

Vehicle Num. : GBF 635M

Make/Model : Toyota Hiace Van Turbo 5 DR-10 / 06

Chassis/Eng# : JTFHT02P000197960/1KD2619760

Accident Date : 26/08/2021

Claim No. :

Reference :

Policy No. : 999993603

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
1		Labour for remove & refix air con system and refill gas	180.00	180.00 120
1		Labour for remove & refix windscreen	120.00	120.00 ✓
1		Labour for remove & refix dashboard	300.00	300.00 200 250
1		Labour for repair light wiring	60.00	60.00 30 40
1		To check from wiring & front Headlamp	40.00	40.00 40 20
1		To dismantle & refix cabin LH handside carpet & timing	160.00	160.00 80 120
1		To respray paint from affected portion	1,500.00	1,500.00 1400
1		To straighten & knock & cut affected panel & renew recommend Parts	1,800.00	1,800.00 1600 1700
1		To dismantle & refix rear cabin timing & garnish to enable repair	45.00	45.00 20
1		to spray paint LH rear portion	800.00	800.00 X
		Labour Total S\$:		5,005.00 3500
				3790

14743.8

~~14500.8~~

E. & O.E.

Total S\$: 15,958.80
 Excess Amount S\$: 1,000.00
 Net Amount S\$: 14,958.80
 GST @ 7% S\$: 1,047.12
 Amount Due S\$: 16,005.92

=====

12 DAYS



for KIM SENG TECK MOTOR WORKS

Liok Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised by Repairer

Signature:

Date: